## HONG SENG ASSEMBLY SDN BHD

## NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	energy : Disel

VEHICLE	Static vertical forces : 6523 daN				
HV	Main	Emergency 1	Emergency 2	Parking Brake	
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 3777 daN 59 % (2) 10 % (1) 7 %				

AXLE (1)	Le	ft	Ax	Le	Rig	ght
Side Slip vertical static force	2267	daN	<b>+2.8</b> 4568	m/km daN	2301	daN
SERVICE BRAKE wheel locked Braking force Efficiency Dissymetry Unbalance	1338 59	daN %	le 2604 57 7	ft daN % %	1266 55	daN %

AXLE (2)	Le	Left		Axle		Right	
vertical static force SERVICE BRAKE	928	daN	1955	daN	1027	daN	
wheel locked Braking force	547	daN	rig 1173	ght daN	626	daN	
Efficiency Dissymetry	59	%	60	%	61	%	
Unbalance			10	%			

OPACITY			
	Absorption OPACITY K	9.00 % 0.18 m-1	
	Max engine speed	0 rpm	

<b>000</b> GOOD	000 ACCEPT. <u>0</u>	00 BAD	(0) Axle		
	V 3.0.6.4				