HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

Operator	ZUL
Vehicle	
	energy : Disel

VEHICLE Static vertical forces : 2805 daN						
HV	Main	Emergency 1	Emergency 2	Parking Brake		
Axles Breaking force Efficiency Unbalance Dissymetry	1+2 2399 daN 63 % (2) 13 % (2) 7 %					

AXLE (1)	Le	ft	Axle		Right	
Side Slip vertical static force SERVICE BRAKE	880	daN	-2.9 1811	m/km daN	920	daN
wheel locked Braking force	588	daN	le 1169	ft daN	610	daN
Efficiency Dissymetry Unbalance	65	%	65 2 4	% % %	66	%

AXLE (2)	Left		Axle		Right	
vertical static force SERVICE BRAKE	450	daN	970	daN	521	daN
wheel locked Braking force	283	daN	1e 588	eft daN	305	daN
Efficiency Dissymetry	52	%	61 7	% %	59	%
Unbalance			13	%		

OPACITY			
	Absorption OPACITY K	10.00 % 0.23 m-1	
	Max engine speed	0 rpm	

000	GOOD	000 ACCEPT.	000 BAD	(0) Axle	
		v 3.0.	6.4		PAGE 1/1