S4522 CNMMT FRV1325 GMME→KTEB

Attention: This route has not yet been filed and is subject to change. Please confirm routing with ARINCDirect or ATC prior to flight.

CREW COMP: FLTDECK CABIN

LUTAK 38N020W 42N030W 45N040W 46N050W SUPRY GRAYY BITRA Q475 TUSKY

RVSM	GND:	LH	SB	RH	TOO	: C	LH	SB	RH	1H:	LH	SB	RH
CHK	2H :	LH	SB	RH	3н	:	LH	SB	RH	4H:	LH	SB	RH
FEET	5H :	LH	SB	RH	6Н	:	LH	SB	RH	TOD:	LH	SB	RH
PERFO:	RMANCI	E CAR	D: T/	O RWY			CON	IDITION	J: [] DRY	[]W	ET [] CONT.
ASS T	EMP	V1	VR	V2	VT		ATOW	I	T/	O TRIM	VA	.PP	VREF
PERFO:	RMANCI	E CAR	D: LD	G RWY			CON	IDITION	1: [] DRY	[]W	ET [] CONT.
RCAM:		VAPP	:	VREF	:		ALW	I:	LDT	A:	Me	ters	
ATIS	DEP:												

ATIS ARR:

IDENT	LAT /LONG						TIME		MINREQ	FF
FREQ		FL	W/V	TAT	GS	REM	ACC		REMAIN	RMK
FIR								ATO	ACT	
0) # -=	12724 00 5							!	_	!
GMME	N34 03.1			!	!					
	W006 45.1			ı		333	861		23131	
DEIO 1	12724 00 0	1505		1000	1000	10000	110 00	!	1 22070	10000
RW21	N34 03.9						00:00		22079	10000
	W006 44.5	1003	081/012	2 +2/	1000	3336	10:00		23131	
ME CO1	N33 52.0	LDTC	/1 D	1102	LCIP	10012	10.00		_ <u></u> 21332	1 = 0.2.4
ME601							10:08			13934
	W006 45.0	1090	030/011	11-06	ICTR	13324	10:08		22384	
DICMI	IM33 30 0	IDICA	//1 D	1200	LCIP	10015	10.02	ļ	121007	10105
DISMI	N33 38.8						0:02		21007	10133
CMANA	W006 53.6		083/020	J - U 9	ICTR	13309	, 10:10		22059	
GMMM	CASABLANCA	UIK								
CAV	IN33 21 2	I D O 7 I	5 5500	1260	LCIP	10040	110.05	!	120402	16970
SAK									120403	100/8
	W007 40.6		088/02	1-44	ICTR	13269	,10:15		21455	
GMMM	CASABLANCA	UIK								
OD73/7	INDO FO C	LITTIO	2000	1216	LCTP	10040	110.05		110074	14067
ODAXA									119974	1496/
	W008 14.5	1408	210/006	01-64	ICTR	13229	10:20		21026	
TOC	IN34 00 4		1000	1310	LCIP	10014	10.02	!	110052	13015
TOC	N34 09.4								19853	
	W008 26.4	1430	/		ICTB	13215	10:22		20905	
T A DMO	IN3/ 10 1	IIIU O	20 1000	1316	1160	10001	10.00		110017	12740
LAPNO	N34 10.1 W008 27.2								19847 20899	12/48
	WUUO 2/.2	1430	322/013	71-63	1454	13214	10:22		1 2 0 0 9 9	
TRATII	N34 26.7	IIIU Q	20 1100	1316	1160	10023	110.03	!	_ <u></u> 19701	12827
IDALU	W008 47.3									12021
	WUU8 4/.3	1430	01//014	1-04	1401	12131	10:26		20753	
BEVAT	N35 58.0	I DCm	1100	1307	1160	10150	110.21		_' <u></u> 18722	12820
DEVAT	W011 26.9								118722	12020
T.PPC	LISBON FIR	1430	033/011	1 - 04	1400	10001	10:40		1 1 2 / / 4	
TILLC	TIODON LIK									
VAREM	N36 32.9	I DCT	1100	129/	1460	10097	110.12		_' <u></u> 18144	12793
V 1 1 1 1 1 1 1	W013 19.4								119196	12773
T.DDC	LISBON FIR	1430	030/000	00	1 1 / 0	12334	. 10.33		1 1 2 1 3 0	
шттс	TIODON LIK								1	
LUTAK	N37 00.0	I DCT	1100	1292	1468	10085	10.11	·	_\ <u></u> 17640	12780
TOIM	W015 00.0								118692	
LPPO				1-04	140/	12049	,11.10		1 10032	
TLLO	DANIA MAKIA	CLAI	VIC LIK							
3820N	N38 00.0	I DCm	1100	1200	1167	10246	0:32		_' <u></u> 16162	12754
302UN	W020 00.0								117214	12/34
T.PPO	SANTA MARIA			-1-05	1400	12003	11:42		1 1 / 2 1 4	
пего	DANIA MAKIA	CEAL	ATC LTK							
									_ '	·

IDENT							MINREQ		
FREQ FIR	FL	W/V :	FAT GS	REM A		ATO	REMAIN ACT 	RMK 	
SC	N38 07.3 S-CLB W020 15.7 450						 16044 17096	•	
42301	N42 00.0 DCT	1100 1	3061474	1050511	ا اا :10:		 12951	 2659	
12501	W030 00.0 450 2						114003		
SC	N42 08.1 S-CLB W030 22.8 470						12814 13866	 3147 	
	N45 00.0 DCT W040 00.0 470 2 GANDER OCEANIC FIR	242/049 -					10140 11192 	 2645 	
	N46 00.0 DCT W050 00.0 470 2 GANDER OCEANIC FIR	274/050 -					 07679 08731 		
	7 N45 30.0 DCT W052 00.0 470 2 GANDER DOMESTIC FIR	280/053 -					 07170 08222 	•	
	N45 44.8 DCT	1100 2					 06008 07060	 2463	
CZQM	MONCTON FIR	219/000 -	-00 415	1089715	0 C : 			 	
	N45 06.4 DCT W061 52.7 470 2						04707 05759 	2415 	
SCOTS	N44 30.0 Q475 W064 00.0 470 2						04144 05196	 2371 	
	N43 33.9 Q475 W067 00.0 470 2 BOSTON ARTCC						 03330 04382 		
SC KZBW	N43 18.9 S-CLB W067 52.9 510 BOSTON ARTCC						03057 04109	 2544 	
COPLY	N42 29.9 DCT W070 33.5 510 2						 02360 03412 	 2206 	
BOS	N42 21.4 DCT	1700 2 279/080 -	261 472				02246	2192	

IDENT FREQ FIR	LAT /LONG 	AWY FL	MORA W/V			TIME ACC		MINREQ REMAIN ACT	FF RMK
BAF 113.0	N42 09.7 W072 43.0	DCT 510	4700 277/078			0:12 7:23		01815 02867 	2184
MOBBS	N42 07.5 W073 15.6	DCT 510	4800 274/077			0:04 7:27	 	01681	2170
TOD	N42 05.5 W073 43.8	 510				0:03 7:30		01566 02618 	 2173
SAGES	N42 02.8 W074 19.2	DCT 417	5200 270/104			0:04 7:35		01502	880
FILPS	N41 56.5 W074 23.7	V489 384	5200 264/125			0:01 7:36		01488	759 759
WEARD	N41 45.7 W074 31.5	V489 306	5200 254/080			0:02 7:38		01462 02514 	 799
CAMMO	N41 37.5 W074 33.1 NEW YORK ART		5200 264/061			0:01 7:39		01445	850
HUO 116.1 KZNY	N41 24.6 W074 35.5 NEW YORK ART		5200 268/058			0:02 7:41		01416	917 917
LEMOR		V489 163	5200 267/058			0:01 7:42		01398	962
COATE	N41 08.2 W074 41.7	V489 122	5200 264/048			0:02 7:44		01368	1034
RW01	N40 50.4 W074 03.6	DCT 000	279/028			0:13 7:56		01048	 1513
KTEB	N40 51.0 W074 03.7	DCT 000	279/028			0:00 7:56		 01048 02100 	 0
CLIMB DESCEI			121 123	NM NM	407 L:		'	'	'

(FPL-FRV1325-IM

-GLF5/M-SDFGHIJ1J5RWXYZ/LB1D1

-GMME0900

-N0468F430 BISMI1B BISMI R975 SAK UH899 IBALU DCT BEXAL DCT VABEM DCT LUTAK/M083F430 DCT 38N020W/M083F450 DCT 42N030W/M083F470 DCT 45N040W DCT 46N050W/N0479F470 DCT SUPRY DCT GRAYY DCT BITRA Q475 TUSKY/N0472F510 DCT COPLY DCT BOS DCT BAF DCT MOBBS DCT SAGES V489 COATE DCT

-KTEB0756

-PBN/A1B1C1D101S1T1 DAT/1FANS2PDC CPDLCX SUR/260A CANMANDATE REG/CNMMT EET/LPPC0047 LPPO0110 38N020W0142 42N030W0254 CZQX0357 45N040W0357 46N050W0455 CZQM0535 KZBW0643 KZNY0740 SEL/EJDG CODE/0200AC OPR/Royal Moroccan Air Force)

REMARKS:

FLIGHT LOG FRV1325 DATE: 22Jan24 TIME: 1433 UTC

RAIM Prediction for 23-JAN-2024
RAIM computation performed using TSO 129 at mask angle of 5.0 with FD.
Important: RAIM prediction does not take ground-based interference into account.
Always check GPS Notams in addition to the RAIM prediction computation.
Enroute: No Outage
(GMME) GPS NPA: No Outage
(KTEB) GPS NPA: No Outage

WGS84 Great Circle Distance: 3155 nm / EU-ETS Benchmark Distance: 5938 km (3206 nm)

Load Manifest CNMMT, FRV1325, G-550, BR710

Departure Airport: GMME

Destination Airport: KTEB Date of Flight: 23-Jan-2024


			14 (II)	(0/88 4 2)	
Item			Mass(lbs)	cg(%MAC)	Last Minute Change
Basic Empty Mass (BEM)			47409	43.82	
Pilots			510		
Aircraft Items			912		
Cabin Crew			0		
Dry Operating Mass (DON	M)		48897	39.84	
Passengers			0		
Passenger 1	0 lbs Passenger 2	0 lbs			
Passenger 3	0 lbs Passenger 4	0 lbs			
Passenger 5	0 lbs Passenger 6	0 lbs			
Passenger 7	0 lbs Passenger 8	0 lbs			
Passenger 9	0 lbs Passenger 10	0 lbs			
Passenger 11	0 lbs Passenger 12	0 lbs			
Passenger 13	0 lbs Passenger 14	0 lbs			
Passenger 15	0 lbs				
Cabin Cargo			0		
Cargo			0		
Zero Fuel Mass (ZFM)			48897	39.84	
ZFM Fwd CG Limit				34.5	
ZFM Aft CG Limit				45.0	
Fuel			23431		
Ramp Mass (RM)			72328	29.76	
Taxi			300		
Takeoff Fuel			23131		
Takeoff Mass (TOM)			72028	29.79	
Takeoff Trim (20 DEG FLA	PS)		11.58		
Takeoff Limit			Not Calculated		
Maximum Allowable Take	off Mass (MATOM)		Not Calculated		
Enroute	,		21031		
Landing Mass (LDM)			50997	38.96	
Landing Limit			Not Calculated		
· ·	/aluga with a *** Dan	-	Mass or og that	Evacado a Lin	

< Values with a *** Denotes a Mass or cg that Exceeds a Limit >

Pilot In Command Signature:	
Second in Command Signature:	
Other Crew Member	
Signature:	
Number of Bossensors	3
Number of Passengers: Trip Number: * PIC Comments:	0

Load Manifest CNMMT, FRV1325, G-550, BR710

Departure Airport: GMME Destination Airport: KTEB Date of Flight: 23-Jan-2024



Zero fuel gross weight CG must be within the allowable Zero Fuel Gross Weight CG Envelope. The fueled airplane CG will then be within limits for all fuel loads.

-			-
Perfo	rma	nce	Data

Performance data could not be computed.

FlightRisk Assessment

GMME at 0900Z 23 Jan to KTEB at 1656Z

Computed On 22 Jan 2024 1434Z

> ID 5933737


CNMMT (GLF5) Tail

Ruleset EASA OPS

General Advisories



General



The planned sortie duration is greater than 6 hrs.

You may need to select a destination alternate.

No advisories for Pilot, Pre-Flight, Taxi Out, Departure, Enroute, Arrival, Approach, Landing, Taxi In.

GMME Advisories (Departure)

No Departure advisories for GMME.

KTEB Advisories (Arrival)

No Arrival advisories for KTEB.

GMME

RABAT/SALE INTL

Depart 23 Jan 2024 0900Z 10:00 AM local

GMME Weather

DAY **TEMPERATURE CEILING** COVER VISIBILITY PHENOMENA WINDS Sunrise: 0729Z (8:29 9° C AM) Unlimited 4.35 SM None Reported 100° 4KTS Clear 5° C Dew Point Sunset: 1747Z (6:47 PM)

METAR

GMME 221430Z 04009KT 360V080 6000 NSC 20/08 Q1030 NOSIG

Retrieved from NOAA at 22 Jan 2024 1434Z

TAF

TAF TAF GMME 221100Z 2212/2318 04009KT 6000 NSC

TEMPO 2218/2310 10004KT 7000 NSC

BECMG 2312/2316 36010KT

Retrieved from NOAA at 22 Jan 2024 1434Z

GMME Runway Performance

	03	21
Crosswind	4	-4
Headwind	1	-1
Warnings		

GMME Safety NOTAMs

	y NOT AWIS
Class	Text
Aerodrome	Ground Ops A0963/23 Effective 15 Dec 2023 0800Z Q) GMMMQFAHG/IV/M/A000/999/3403N00645W005 A) GMME B) 2312150800 C) 2403131800 D) 0800-1800 E) GRASS CUTTING ON THE MVT AREA (EDGE OF THE RUNWAY AND TAXIWAYS) PRESENCE PERSONS AND EQPT WILL BE VACATED 15MN BEFORE EACH MVT. CAUTION RECOMMENDED.
Aerodrome	A0979/23 Effective 21 Dec 2023 1734Z Q) GMMWQMKHW/IV/MA/000/999/3403N00645W005 A) GMME B) 2312211734 C) 2403201900 D) 0800-1900 E) LIGHTING WORKS RELATED TO THE REALIZATION OF A NEW ACFT PRKG AREA. PRESENCE PERSONS AND EQPT WILL BE VACATED 15MN BEFORE EACH MOV. CAUTION RECOMMENDED.
	Takeoff and Landing
Obstruction	A0804/23 Effective 30 Oct 2023 1134Z Q) GMMM/QOBCE/IV/MAE/000/004/3402N00645W001 A) GMME B) 2310301134 C) 2401282359 E) OBST (CRANE7)(340207.18N 0064519.49W) ERECTED 38M BEYOND THR 03 AND 625M RIGHT RCL, 18M AGL, 106M MSL. LIGHTED DAY AND NIGHT LENGTH OF THE BOOM =50M CAUTION RECOMMENDED GND-FL004
Obstruction	A0805/23 Effective 30 Oct 2023 1200Z Q) GMMM/QOBCE/IV/MAE/000/015/3402N00645W001 A) GMME B) 2310301200 C) 2401282359 E) OBST (CRANE6)(340209.47N 0064518.66W) ERECTED 109M BEYOND THR 03 AND 608M RIGHT RCL, 30M AGL, 114.83M MSL. LIGHTED DAY AND NIGHT LENGHT OF THE BOOM =50M CAUTION RECOMMENDED. GND-FL015
Obstruction	A0806/23 Effective 30 Oct 2023 1202Z Q) GMMM/QOBCE/IV/M/AE/000/015/3402N00645W001 A) GMME B) 2310301202 C) 2401282359 E) OBST (CRANE5)(340212.13N 0064516.70W) ERECTED 205M BEYOND THR 03 AND 608M RIGHT RCL, 25M AGL, 109.83M MSL. LIGHTED DAY AND NIGHT LENGHT OF THE BOOM =50M CAUTION RECOMMENDED. GND-FL015
Obstruction	A0807/23 Effective 30 Oct 2023 1204Z Q) GMMM/QOBCE/IV/M/AE/000/004/3402N00645W001 A) GMME B) 2310301204 C) 2401282359 E) OBST (CRANE4)(340214.38N 0064515.89W) ERECTED 275M BEYOND THR 03 AND 589M RIGHT RCL, 18M AGL, 106M MSL. LIGHTED DAY AND NIGHT LENGTH OF THE BOOM =50M CAUTION RECOMMENDED GND/FL004
Obstruction	A0808/23 Effective 30 Oct 2023 1205Z Q) GMMM/QOBCE/IV/M/AE/000/004/3402N00645W001 A) GMME B) 2310301205 C) 2401282359 E) OBST (CRANE3)(340213.42N 0064519.21W) ERECTED 205M BEYOND THR 03 AND 531M RIGHT RCL, 22M AGL,113M MSL. LIGHTED DAY AND NIGHT LENGTH OF THE BOOM =50M CAUTION RECOMMENDED GND-FL004
Obstruction	A0809/23 Effective 30 Oct 2023 1206Z Q) GMMM/QOBCE/IV/M/AE/000/004/3402N00645W001 A) GMME B) 2310301206 C) 2401282359 E) OBST (CRANE2)(340211.35N 0064520.73W) ERECTED 131M BEYOND THR 03 AND 531M RIGHT RCL, 18M AGL, 106M MSL. LIGHTED DAY AND NIGHT LENGTH OF THE BOOM=50M CAUTION RECOMMENDED GND-FL004
Obstruction	A0810/23 Effective 30 Oct 2023 1207Z Q) GMMMQOBCE/IV/MAE/000/004/3402N00645W001 A) GMME B) 2310301207 C) 2401282359 E) OBST (CRANE1) (340208.94N 0064522.50W) ERECTED 44M BEYOND THR 03 AND 531M RIGHT RCL, 22M AGL ,110M MSL. LIGHTED DAY AND NIGHT LENGTH OF THE BOOM =50M CAUTION RECOMMENDED GND-FL004

Obstruction	A0839/23 Effective 10 Nov 2023 0001Z Q) GMMM/QOBCE/IV/M/AE/000/010/3401N00648W001 A) GMME B) 2311100001 C) 2402082359 E) OBST CRANE ERECTED ATOP MED 6 TWR LOCATED AT 340108.7N 0064818.1W ALTITUDE: 257.71M HEIGHT: 252.21M
	Approach
Procedure	A0835/23 Effective 07 Nov 2023 1418Z Q) GMMMQPIAW/I/NBO/A/000/999/3403N00645W005 A) GMME B) 2311071418 C) PERM E) ILSY RWY 21 WEF 24 MAR 2022 (AD2 GMME-39-2-2 AND DATA) SUPPRESSED
Procedure	V0468/23 Effective 02 Nov 2023 0001Z Q) GMMM/QPICH/I/BO/A/000/999/3403N00645W005 A) GMME B) 2311020001 C) 2401250001 E) [US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED ILS Z RWY 2 CAT ABCD MINIMA TO READ 640/1200M 402 (400-1200M).
Procedure	V0469/23 Effective 02 Nov 2023 0001Z Q) GMMM/QPICH/I/BO/A/000/999/3403N00645W005 A) GMME B) 2311020001 C) 2401250001 E) [US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED ILS YRWY 2 CAT ABCD MINIMA TO READ 640/1200M 402 (400-1200M).
Procedure	V0545/23 Effective 04 Dec 2023 1059Z Q) GMMWQPIAU/I/BO/A/000/999/3403N00645W005 A) GMME B) 2312041059 C) 2402220001 E) [US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE NOT AUTHORIZED VOI RWY 21.
Procedure	V0546/23 Effective 04 Dec 2023 1100Z Q) GMMM/QPIAU/I/BO/A/000/999/3403N00645W005 A) GMME B) 2312041100 C) 2402220001 E) [US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE NOT AUTHORIZED ILS RWY 21.
Procedure	V0547/23 Effective 04 Dec 2023 1110Z Q) GMMM/QPIAU/I/BO/A/000/999/3403N00645W005 A) GMME B) 2312041110 C) 2402220001 E) [US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE NOT AUTHORIZED ILS RWY 21.

16 NOTAMs retrieved from Federal NOTAM System (FAA) at 22 Jan 2024 1434Z.

GMME Risk Ratings

There are no risk ratings for this airfield.

Enter a Risk Rating

GMME Procedures

No information to display

View all Procedures

GMME Services

City RABAT

Country Morocco

Elevation 272 feet above sea level

Location 34° 3′ N, 6° 45′ W

Time Zone Africa/Casablanca

UTC Offset UTC 0 hours

Daylight Savings UTC +1 hours

Tower YES

Operations Schedule NON 24 HOURS INCLUDING HOLIDAYS RAMADAN : MON-FRI : 0900-1430

Fuel 100LL, A1

ARFF Class 8

Airport of Entry YES

Military/Civil Joint Use YES

Military Landing Rights NO

KTEB

TETERBORO

Arrive 23 Jan 2024 1656Z 11:56 AM local

KTEB Weather

DAY COVER TEMPERATURE CEILING VISIBILITY PHENOMENA WINDS Sunrise: 1214Z (7:14 Broken at 4500 FT 3° C AM) 4500 FT 6 SM None Reported 280° 5KTS AGL -2° C Dew Point Sunset: 2201Z (5:01 PM)

METAR

KTEB 221351Z 26005KT 10SM CLR M03/M10 A3057 RMK AO2 SLP350 T10331100

Retrieved from NOAA at 22 Jan 2024 1434Z

TAF

KTEB 221421Z 2214/2318 26005KT P6SM FEW250

FM221800 23009KT P6SM SCT200

FM230700 VRB03KT P6SM BKN070

FM231500 28005KT P6SM BKN045

Retrieved from NOAA at 22 Jan 2024 1434Z

KTEB Runway Performance

	01	19	24	06
Crosswind	-5	5	3	-3
Headwind	0	0	4	-4
Warnings	X	X		

KTEB Safety NOTAMs

Class	Text
	Ground Ops
Aerodrome	01/004 Effective 03 Jan 2024 0206Z Q) KZNY/QFAXX/IV/NBO/A/000/999/4051N07403W005 A) KTEB B) 2401030206 C) 2402010459 E) AP WILDLIFE HAZARD DEER, FOX
	Takeoff and Landing
Aerodrome	01/114 Effective 24 Jan 2024 1230Z Q) KZNY/QMRLC/IV/NBO/A/000/999/4051N07403W005 A) KTEB B) 2401241230 C) 2401241700 E) RWY 01/19 CLSD
	Departure
Procedure	2/5319 Effective 16 Mar 2022 2044Z Q) ZNY/undefined/NBO/A/000/999/4051N07403W025 A) KTEB B) 2110071416 C) 2205191416EST E) SID TETERBORO, TETERBORO, NJ. TETERBORO FOUR DEPARTURE DIXIE AND WHITE DEPARTURES: NA EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH GPS, COL VOR OUT OF SERVICE.
Procedure	3/5061 Effective 26 Sep 2023 1508Z Q) ZNY/QPDCH/I/NBO/A/000/999/4051N07403W025 A) KTEB B) 2110071415 C) 2205191415EST E) SID TETERBORO, TETERBORO, NJ. TETERBORO FOUR DEPARTURE COATE, ELIOT, NEWEL, ZIMMZ DEPARTURES: NA EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH GPS.,

	SAX VOR OUT OF SERVICE.	
Procedure	3/6328 Effective 14 Dec 2023 2232Z Q) ZNY/QPDCH/I/NBO/A/000/999/4051N07403W025 A) KTEB B) 2207070308 C) 2302160308EST E) SID TETERBORO, TETERBORO, NJ. TETERBORO FOUR DEPARTURE DEPARTURE PROCEDURE NOTE: BREZY DEPARTURE NA EXCEPT FOR AIRCRAFT EQUIPPED WI SUITABLE RNAV SYSTEM WITH GPS, IGN VOR/DME OUT OF SERVICE.	
Procedure	3/6817 Effective 28 Nov 2023 2132Z Q) ZNY/QPDAO/I/NBO/A/000/999/4051N07403W025 A) KTEB B) 2205162328 C) 2212262328EST E) SID TETERBORO, TETERBORO, NJ. TETERBORO FOUR DEPARTURE NOTE: PARKE DEPARTURE VIA BWZ R-250 NA EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH GPS, BWZ VOR/DME OUT OF SERVICE.	
3/8567 Effective 21 Dec 2023 1710Z Q) KZNY/undefined/NBO/A/000/999/4051N07403W005 A) KTEB B) 2312211710 C) 2405061710EST E) TEB TETERBORO, TETERBORO, NJ. TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 8A ADD TAKEOFF OBSTACLE NOTE: RWY 19, TEMPORARY CRANE 590FT FROM DER, 2FT LEFT OF CENTERLINE, 30FT AGL/35FT MSL (2021-AEA-2062-NRA). ALL OTHER DATA REMAINS AS PUBLISHED.		
	Approach	
Procedure	3/1005 Effective 10 Aug 2023 0901Z Q) KZNY/QPIXXI/NBO/A/000/999/4051N07403W005 A) KTEB B) 2308091518 C) 2403201517EST E) TEB TETERBORO, TETERBORO, NJ. RNAV (GPS) X RWY 6, AMDT 3 CHANGE PLANVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVALS AT COATE ON V252 NORTHBOUND AND V116-188, T218 NORTHWEST BOUND.	
	Landing	
Aerodrome	12/061 Effective 13 Dec 2023 1622Z Q) KZNY/QLPAS/IV/BO/A/000/999/4051N07403W005 A) KTEB B) 2312131622 C) 2410312359 E) RWY 01 PAPI UNUSABLE	
Aerodrome	12/062 Effective 13 Dec 2023 1651Z RWY 01 VASI (V4R) GPA 3.5DEG AVBL 2312131651-2410312359	
	Unclassified	
Obstruction	01/003 Effective 01 Jan 2024 2158Z Q) KZNY/QOLAS/IV/MAE/000/005/4051N07403W005 A) KTEB B) 2401012158 C) 2402012359 E) TOWER LGT (ASR 1042783) 404817.00N0740626.00W (3.5NM SW TEB) 413.1FT (410.1FT AGL)	
Obstruction	01/061 Effective 16 Jan 2024 0059Z Q) KZNY/QOLAS/IV/MAE/000/005/4051N07403W005 A) KTEB B) 2401160059 C) 2402012359 E) TOWER LGT (ASR 1042784) 404813.00N0740626.00W (3.5NM SW TEB) 413.1FT (410.1FT AGL)	
Obstruction	01/133 Effective 22 Jan 2024 1341Z Q) KZNY/QOBXX/IV/M/000//4051N07403W005 A) KTEB B) 2401221341 C) 2401292200 E) CRANE (ASN 2023-AEA-15636-OE) 404857N0740353W (2.1NMS TEB) 134FT (125FT AGL) FLAGGED AND LGTD	
Obstruction	12/029 Effective 06 Dec 2023 1348Z Q) KZNY/QOLAS/IV/MAE/000/003/4051N07403W005 A) KTEB B) 2312061348 C) 2401312359 E) TOWER LGT (ASR 1040101) 404914.80N0740404.00W (1.8NMS TEB) 237.9FT (237.9FT AGL) U/S	
Obstruction	12/113 Effective 31 Dec 2023 2317Z Q) KZNY/QOLAS/IV/MAE/000/004/4051N07403W005 A) KTEB B) 2312312317 C) 2402292359 E) TOWER LGT (ASR 1045377) 404758.00N0740632.00W (3.8NM SW TEB) 311.0FT (306.1FT AGL)	
Obstruction	12/114 Effective 31 Dec 2023 2317Z Q) KZNY/QOLAS/IV/MAE/000/004/4051N07403W005 A) KTEB B) 2312312317 C) 2402292359 E) TOWER LGT (ASR 1045373) 404748.00N0740616.00W (3.8NM SSW TEB) 311.0FT (306.1FT AGL)	
Obstruction	12/115 Effective 31 Dec 2023 2318Z Q) KZNY/QOLAS/IV/MAE/000/005/4051N07403W005 A) KTEB B) 2312312318 C) 2402292359 E) TOWER LGT (ASR 1045375) 404753.00N0740623.00W (3.8NM SW TEB) 410.8FT (405.8FT AGL)	

KTEB Chart Supplement

N.I.	KTFR	Heliconter Routes	

NJ, KTEB Dalton 2 Departure Procedure

NJ, KTEB Helicopter Routes

NJ, KTEB Dalton 2 Departure Procedure

Remarks

Special Notices

CLSD TO MOTORLESS ACFT - UNCTLD ACFT & ULTRALIGHT ACTIVITY EXCEP BY PRIOR PERMISSION.

DLY CONS CONST ACT ALL QUADRANTS.

ACFT CAPABLE OF OPERATING ABV 100,000 POUNDS MUST SUBMIT CERTIFICATION TO AMGR VERIFYING AIRCRAFT OPERATING WEIGHT IS LESS THAN 100,000 LBS. CONTACT AIRPORT OPERATIONS AT 201-288-1775 FOR FORMS.

TEB RNAV (GPS) X RWY 06 IS PRIM RNAV APCH TO RWY 06.

ALL ACFT AVOID HOSPITAL 1.7 MILE NORTH OF RWY 01/19.

DEER AND BIRD ACT ON AND INVOF ARPT.

HEL OPNS OVER RESIDENTIAL AREAS BLO 1000 FT MSL SHOULD BE AVOIDED.

ACFT & HELICOPTER NOISE ABATEMENT RULES IN EFF; CTC ARPT NOISE ABATEMENT OFC 201-393-0399/288-1775 FOR COPY OF PROCEDURES & RULES PRIOR TO ARR. RY 24 NOISE CRITICAL RY MAX NOISE LIMIT OF 80 DB BETWEEN 2200-0700 & 90 DB ALL OTR HRS.

STAGE 1 ACFT NOT PERMITTED TO OPR AT TETERBORO ARPT.

A26 ARFF INDEX B EQUIPMENT COVERAGE PRVDD.

RWY 01/19 DTHR CNTRLN LGTS OTS INDEFLY.

RWY 01 67 FT TREE DIST 1200 FT, 400 FT RIGHT, 16:1 BASED ON DTHR.

RWY 19 APCH RATIO 25:1 TO DTHR.

A82 ARPT OPS FREQUENCY 130.575.

E147 TPA 1500 FT MSL FOR LARGE/TURBINE ACFT; 1000 FT MSL FOR ALL OTHERS.

EMAS NON-STD ARRESTING GEAR/SYSTEM: ENGINEERED MATERIALS ARRESTING SYSTEM (EMAS) 250 FT IN LENGTH BY 170 FT WIDTH LCTD AT DEP END RWY 06.

ENGINEERED MATERIALS ARRESTING SYSTEM (EMAS) 355 FT IN LENGTH BY 162 FT WIDTH LCTD AT DEP END RWY 19.

ENGINEERED MATERIALS ARRESTING SYSTEM (EMAS) 348 FT IN LENGTH BY 162 FT WIDTH LCTD AT DEP END RWY 24.

FOR RADAR SVC BLO 1800 FT CTC TEB ATCT FREQ 119.5.

KTEB Risk Ratings

Risk	Date	Pilot Comments				
	Taxi Out					
No rece	No recent risk ratings.					
		Departure – 30 day high: 0, 1 year high: 0				
		On Departure STOP climb at 1500ft sharp.				
5	30 Jan 2023	GLF6 24 RUUDY SIX (RNAV) <u>Vote Up</u> <u>Vote Down</u>				
		Many errors occur when using the Dalton 19 Departure. The Teterboro Tower and the Teterboro Users Group (TUG) have published training material discussing the procedure and the common errors that have been observed. Details are available from flight planning service providers. The highlights for using this procedure are:				
3	10 Oct 2011	1. The crew must specifically request this DP from Clearance Delivery. 2. The DP is a VFR departure and you become IFR after a clearance is received from New York Departure. 3. The initial turn must be made after climbing through 200 feet and within 3 DMF of the TER VOR.				
		3. The initial turn must be made after climbing through 800 feet and within 2 DME of the TEB VOR. GLF5 19 VFR Vote Up Vote Down				
2	04 Aug 2010	Used the Dalton 5 departure - VERY easy to get faster than 190 knots on this departure. F900 19 Diverse Departure Vote Up Vote Down				
2	31 Aug 2011	GLEX 01 TETERBORO SIX Vote Up Vote Down				
3	26 May 2010	H25B 24 RUUDY TWO (RNAV) Vote Up Vote Down				
2	23 May 2012	F900 24 RUUDY FOUR (RNAV) Vote Up Vote Down				
		Arrival – 30 day high: 0, 1 year high: 0				
3	08 May 2019	Glider operations in the vicinity of the "MUGZY†intersection on the "Wilkes Barre 4 Arrival.â€ There are two gliderports south or the fix. GL5T WILKES-BARRE FOUR				
		Vote Up Vote Down				

2	09 Feb 2016	ATC required descent 58 miles before calculated top of descent. Resulted in approximately 200 extra lbs fuel burn. LJ45 WILKES-BARRE FOUR			
		Vote Up Vote Down			
2	03 Oct 2017	Various step down fixes. Busy NYC airspace. F2TH JAIKE THREE (RNAV) Vote Up Vote Down			
2	30 Jun 2010	F900 WILKES BARRE THREE Vote Up Vote Down			
		Approach – 30 day high: 0, 1 year high: 0			
4	14 Feb 2017	ATC typically clears for the ILS 6, saying Maintain 2,000 until established, cleared for the ILS 6 approach. They don't mention the MANDATORY crossing altitude at Dandy of 1,500'. If you maintain 2,000, and capture the GS from that altitude, you will be above Dandy by about 200', which potentially puts you in harms way of EWR traffic crossing overhead. Take time to brief this approach carefully, and make sure you cross Dandy at 1,500, intercept the GS after that fix.			
		GLF4 ILS OR LOC RWY 06 Vote Up Vote Down			
2	09 Feb 2016	Prior to the end of the STAR at STW, ATC cleared us direct to VINGS then about 5 miles from VINGS gave a vector of 080 to intercept the localizer and descend to 2000'. This required a quick switch from an LNAV mode to a HDG and VOR/LOC display and arming the approach along with selection of VS to descent. With the clearances and switching there was potential to miss the DANDY mandatory crossing restriction at 1500'. The controller reminded us 4 miles prior to DANDY of the restriction. There is potential to remain at 2000' as per the clearance in the vector from STW and intercept the GS, which would result in a DANDY crossing at approximately 1800'. LJ45 LS OR LOC RWY 06			
		Vote Up Vote Down Initiate turn ASAP after TORBY.			
4	03 Oct 2017	Maneuver just outside of the stadium and arena to roll out - 1.6 nm from touch-down at 500 ft. Overflying the stadium permitted when necessary for operational or safety of flight purposes. Fly visual approach as high as 1,300 feet, not at circling minimums. Avoid late/steep turns when maneuvering to Runway 1.			
		F2TH ILS OR LOC RWY 06 Vote Up Vote Down			
		ILS 19 circle to 24. Begin your turn at TUGGZ.			
4	08 Dec 2019	F2TH ILS OR LOC RWY 19 Vote Up Vote Down			
3	04 Nov 2018	ILS 19 glideslope antenna is immediately adjacent to taxiway 19. During VMC conditions, the ILS critical area is not protected, and taxing aircraft can interfere with the glideslope signal. ASRS data indicates that this has caused numerous altitude deviations, especially when flown with the autopilot engaged. [The glideslope signal interference causes the aircraft vertical mode to transition early to glideslope mode while still well below glideslope, resulting in the aircraft climbing above assigned altitude to try to center the electronic glidepath.]			
		GLF4 ILS OR LOC RWY 19 Vote Up Vote Down			
		On the missed procedure for ILS 19 there is a mandotory crossing restriction of 1500 ft at BUBGE.			
2	23 Aug 2020	C25A ILS OR LOC RWY 19 Vote Up Vote Down			
	10 Sep 2018	There are mandatory crossing altitudes. Most importantly while on the approach and near TBERN expect course deflection due the smart turn and course change of 15 degrees.			
3		GL5T RNAV (RNP) Z RWY 06 Vote Up Vote Down			
	47.0 (000)	encountered large flock of canada geese on approach.			
3	17 Oct 2021	F900 RNAV (GPS) RWY 24 <u>Vote Up</u> <u>Vote Down</u>			
	Landing – 30 day high: 0, 1 year high: 0				
		ILS 19 circle to 24. Begin your turn at TUGGZ.			
4	08 Dec 2019	F2TH 24 Vote Up Vote Down Rusy congested airspace Brief early and the roughly KLGA and KEWP are pearly			
4	03 Oct 2017	Busy congested airspace. Brief early and thoroughly. KLGA and KEWR are nearby. F2TH 01 Vote Up Vote Down			
	Taxi In – 30 day high: 0, 1 year high: 0				
2	14 Feb 2017	Crews are cautioned to stop after exiting the runway and contact Ground control prior to further movement on taxiways. Crews have been reported by ATC to FAA for taxiway movement prior to proper clearance from Tower or Ground. GLF4 Vote No. Vote Down			
2	15 Mar 2016	Vote Up Vote Down When airport configuration is landing RWY 06 departing RWY 01 unable to exit RWY 06 via taxiway B due to runway incursion risk. GLF6			
		Vote Up Vote Down			

Enter a Risk Rating

KTEB Procedures









View all Procedures

KTEB Services

City TETERBORO

State New Jersey

Country United States of America

Elevation 8 feet above sea level

Location 40° 51′ N, 74° 4′ W

Proximity 1 mile southwest of city center

Time Zone America/New_York

UTC Offset UTC -5 hours

Daylight Savings UTC -4 hours

Tower YES

Attendance (M/D/H) ALL/ALL/ALL

Lighting SS-SR

Airspace Class D

Operations Schedule 24

Fuel 100LL, A

ARFF Class IV A

Oxygen BULK: HIGH/LOW

BOTTLED

Repairs Airframe: MAJOR

Engine: MAJOR

Airport of Entry NO

Military/Civil Joint Use NO

Military Landing Rights YES

Landing Rights Airport YES

Risk assessment computed on 22 Jan 2024 1434Z.

Information in this report is based on the data available at the time it was run. Links to content outside the report may reference information that is later updated or deleted.

Pilot currency tracking was not enabled for this risk assessment.

View Risk Assessment in FlightRisk

End of FlightRisk Assessment