HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041608 **11/13/2026 1:20 pm**

DJPJ HOLDINGS
15035 E HINSDALE DR. UNIT B
CENTENNIAL, CO 80112
MOBILE:(303) 617-1125
WORK:(303)

2014 AUDI A4
4-1984 2.0L DOHC
VIN : WAUHFAFL5EN043992
Mileage :
Trans : STD
License :

COLR : BLACK

Your Service Writer Today Is: SHOP OWNED Center: SHOP OWNED VEHICLE

Service Requests:

Category Summary	Parts	Labor	Job Total
COMMENTS/NOTES	$0.00	$0.00	$0.00
CHARGING SYS & BATT	$1,016.45	$45.00	$1,061.45
DRIVEABILITY	$0.00	$274.00	$274.00
ENGINE	$0.00	$959.00	$959.00
INSPECTIONS	$0.00	$274.00	$274.00
OIL CHANGE	$88.74	$137.00	$225.74

Technician	Service Description	Parts	Labor	Job Total
TK	**USED VEHICLE INSPECTION: ROAD TEST VEHICLE. VISUALLY INSPECT ALL FLUIDS, FILTERS, BELTS, BATTERY AND HOSES. PERFORM FOUR WHEEL BRAKE INSPECTION. LOAD TEST ALL STEERING AND SUSPENSION COMPONENTS. INSPECT BODY OF VEHICLE FOR DAMAGE AND FUNCTIONALITY OF VITAL BODY RELATED COMPONENTS. SCAN FOR DIAGNOSTIC TROUBLE CODES AND PRINT. CHECK FOR OPEN RECALLS AND SERVICE BULLETINS. COMPLETE A 30-PT INSPECTION SHEET WITH BRAKES & TIRE MEASUREMENTS.**		274.00	274.00
TK	**EURO SYNTHETIC OIL CHANGE FILL WITH FACTORY SPECIFIED QUALITY AND AMOUNT OF OIL-EURO FULL SYNTHETIC OIL TYPE: EURO SYNTHETIC.**	88.74	137.00	225.74

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	5W30 SYNTHETIC	5W30 SYNTHETIC	11.99	4.9	58.75
N	MSL57561	MicroGard Select Oil Filter	29.99	1	29.99

TK	**CHECK ENGINE LIGHT TESTING & ANALYSIS: CUSTOMER STATES THAT CHECK ENGINE LIGHT IS ON; INCLUDES MONITOR ENGINE COMPUTER FOR FAULT CODES AND INSPECT FOR APPLICABLE TECHNICAL SERVICE BULLETINS OR RECALLS. DOCUMENT MODULAR SOFTWARE VERSION. IDENTIFY SOFTWARE UPDATES ADVISED. PERFORM PINPOINT ANALYSIS AND CIRCUIT TESTING.**		274.00	274.00
TK	**TECHNICIAN NOTES: SCANNED VEHICLE AND FOUND FAULT P201400 – INTAKE MANIFOLD RUNNER POSITION SENSOR/SWITCH CIRCUIT, ACTIVE/STATIC.INSPECTED INTAKE MANIFOLD AND FOUND IT HAD BEEN RECENTLY REPLACED. TESTED INTAKE MANIFOLD RUNNER POSITION SENSOR CIRCUIT AND VERIFIED PROPER 5-VOLT REFERENCE AND GROUND. MONITORED SENSOR SIGNAL VOLTAGE WHILE OPERATING INTAKE MANIFOLD RUNNERS AND FOUND SIGNAL REMAINED AT A CONSTANT 5 VOLTS WITH NO CHANGE IN RESPONSE TO RUNNER MOVEMENT.TESTED SIGNAL CIRCUIT WIRING FROM SENSOR CONNECTOR BACK TO ECM AND FOUND NO WIRING FAULTS. REMOVED SIGNAL WIRE TERMINAL FROM ECM CONNECTOR TO ISOLATE CIRCUIT AND VERIFY WHETHER ECM WAS SUPPLYING THE CONSTANT 5 VOLTS. CONFIRMED ECM WAS NOT THE SOURCE OF THE VOLTAGE.REMOVED INTAKE MANIFOLD AND REMOVED RUNNER POSITION SENSOR TO INSPECT SENSOR ENGAGEMENT AND VERIFY MECHANICAL ROTATION OF THE RUNNER SHAFT. CONFIRMED PROPER MECHANICAL OPERATION.DURING INSPECTION, DISCOVERED THE RUNNER POSITION SENSOR ELECTRICAL CONNECTOR CAN PHYSICALLY BE INSTALLED IN EITHER ORIENTATION. FOUND CONNECTOR HAD BEEN INSTALLED INCORRECTLY DURING PREVIOUS INTAKE MANIFOLD REPLACEMENT.CORRECTED CONNECTOR ORIENTATION AND REINSTALLED**		0.00	

Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041608 **11/13/2026 1:20 pm**

DJPJ HOLDINGS
15035 E HINSDALE DR. UNIT B
CENTENNIAL, CO 80112
MOBILE:(303) 617-1125
WORK:(303)

2014 AUDI A4
4-1984 2.0L DOHC
VIN : WAUHFAFL5EN043992
Mileage :
Trans : STD
License :

COLR : BLACK

Your Service Writer Today Is: SHOP OWNED Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total
	INTAKE MANIFOLD. RETESTED SYSTEM AND CONFIRMED PROPER OPERATION. ORIGINAL FAULT CONDITION RESOLVED.			
TK	**R&R INTAKE MANIFOLD**		**959.00**	**959.00**
TK	**REPLACE BATTERY AND REGISTER IT TO THE VEHICLE**	**1016.45**	**45.00**	**1061.45**

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	*985*	*BATTERY TERMINAL PROTECTORS*	*9.99*	*1*	*9.99*
N	*P49AGM*	*BATTERY*	*1006.46*	*1*	*1006.46*

Authorizations

Approved By:	Approval Given To:	Date	Time	Difference	Total Authorized	Method
DUSTIN JOHNSON		11/13/26	11:17 am	$2,922.69	$2,922.69	By Phone
Reason: DJ						

Repair Order Notes

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$1,105.19
TOTAL LABOR	$1,689.00
SUBLET	$0.00
SHOP/HAZMAT	$128.50
SUBTOTAL	$2,922.69
OTHER FEES	$0.00
SALES TAX	$0.00
INVOICE TOTAL	**$2,922.69**
PAID	$0.00
DUE	$2,922.69

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

Thank you for your business!