

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041485**9/16/2026
7:59 am**

2011 BMW X5
6-2993 3.0L DSL
VIN : 5UXZW0C53BL662815
Mileage :
Trans : AUTO
License :

COLR : BLUE
Unit # DIESEL

DJPJ HOLDINGS
14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Service Requests:

<u>Category Summary</u>	<u>Parts</u>	<u>Labor</u>	<u>Job Total</u>
INSPECTIONS	\$0.00	\$274.00	\$274.00
OIL CHANGE	\$403.06	\$137.00	\$540.06

Technician	Service Description	Parts	Labor	Job Total																									
TK	USED VEHICLE INSPECTION: ROAD TEST VEHICLE. VISUALLY INSPECT ALL FLUIDS, FILTERS, BELTS, BATTERY AND HOSES. PERFORM FOUR WHEEL BRAKE INSPECTION. LOAD TEST ALL STEERING AND SUSPENSION COMPONENTS. INSPECT BODY OF VEHICLE FOR DAMAGE AND FUNCTIONALITY OF VITAL BODY RELATED COMPONENTS. SCAN FOR DIAGNOSTIC TROUBLE CODES AND PRINT. CHECK FOR OPEN RECALLS AND SERVICE BULLETINS. COMPLETE A 30-PT INSPECTION SHEET WITH BRAKES & TIRE MEASUREMENTS.		274.00	274.00																									
TK	DIESEL OIL CHANGE Includes oil, filter & Lubrication (Where needed) up to 14 qts 15w-40 Diesel oil *additional qts extra. FILL DIESEL EXHAUST FLUID (IF APPLICABLE). RESET OIL LIFE INDEX. OIL TYPE:DIESEL 15W40.	403.06	137.00	540.06																									
	<table><thead><tr><th><u>Part Number</u></th><th><u>Part Description</u></th><th><u>Part Price Each</u></th><th><u>Quantity</u></th><th><u>Extended</u></th></tr></thead><tbody><tr><td>WP-334274</td><td>OIL FILTER KIT INSER</td><td>51.34</td><td>1</td><td>51.34</td></tr><tr><td>LM 2011</td><td>MOTOR OIL FULL SYNTH</td><td>185.64</td><td>1</td><td>185.64</td></tr><tr><td>LM 2004</td><td>MOTOR OIL FULL SYNTH</td><td>37.12</td><td>3</td><td>111.36</td></tr><tr><td>DEF</td><td>DIESEL EXH. FLUID PLATNUM</td><td>32.19</td><td>1.7</td><td>54.72</td></tr></tbody></table>	<u>Part Number</u>	<u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>	WP-334274	OIL FILTER KIT INSER	51.34	1	51.34	LM 2011	MOTOR OIL FULL SYNTH	185.64	1	185.64	LM 2004	MOTOR OIL FULL SYNTH	37.12	3	111.36	DEF	DIESEL EXH. FLUID PLATNUM	32.19	1.7	54.72			
<u>Part Number</u>	<u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>																									
WP-334274	OIL FILTER KIT INSER	51.34	1	51.34																									
LM 2011	MOTOR OIL FULL SYNTH	185.64	1	185.64																									
LM 2004	MOTOR OIL FULL SYNTH	37.12	3	111.36																									
DEF	DIESEL EXH. FLUID PLATNUM	32.19	1.7	54.72																									

Services Recommended to Customer

REMOVE REAR DIFFERENTIAL AND REPLACE SEALS
REPLACE RIGHT FRONT AXLE BOOTS
REPLACE VACUUM PUMP
EVACUATE AND RECHARGE A/C SYSTEM - R134A
REMOVE & REPLACE HVAC EVAPORATOR
REPLACE CENTER VENT

Parts Recommended To Customer

2	WP-4136843	DIFF. SIDE COVER SEA
1	WP-289292	PINION SHAFT NUT
1	WP-481273	PINION SEAL-REAR
2	7515	ULTRA GUARD LS 75W90 FULL SYN
1	WP-281335	CV BOOT KIT-FRONT IN
1	WP-281336	CV BOOT KIT-FRONT OU
1	WP-378299	VACUUM PUMP
24	R134A	REFRIGERANT BY THE OUNCE
1	7018	A/C OIL W/ DYE PER OUNCE
1	WP-856505	A/C EVAPORATOR W/O E
2	0020	COOLANT GOLD PLUS EXT LIFE GALLONS
1	64 22 9 220 101	CENTER VENT
1	64 22 9 210 705	CENTER VENT

Repair Order Notes

Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041485**9/16/2026
7:59 am**

2011 BMW X5
6-2993 3.0L DSL
VIN : 5UXZW0C53BL662815
Mileage :
Trans : AUTO
License :

COLR : BLUE
Unit # DIESEL

DJPJ HOLDINGS
14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total
------------	---------------------	-------	-------	-----------

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ Date: _____

TOTAL PARTS	\$403.06
TOTAL LABOR	\$411.00
SUBLET	\$0.00
SHOP SUPPLY	\$40.70
SUBTOTAL	\$854.76
OTHER FEES	\$0.00
SALES TAX	\$29.95
INVOICE TOTAL	\$884.71
PAID	\$0.00
DUE	\$884.71

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

**Thank you for your business!**