

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041463

9/14/2026
3:51 pm

2012 PORSCHE CAYENNE
V8-4806 4.8L DOHC
VIN : WP1AC2A23CLA81147
Mileage :
Trans : AUTO
License :
COLR : BLUE
Unit # TURBO

DJPJ HOLDINGS
14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Service Requests:

Category Summary	Parts	Labor	Job Total
COMMENTS/NOTES	\$0.00	\$0.00	\$0.00
ENGINE	\$1,836.65	\$4,521.00	\$1,507.00
INSPECTIONS	\$0.00	\$274.00	\$274.00
MAINTENANCE SERVICES	\$2,236.96	\$602.80	\$2,839.76
OIL CHANGE	\$405.36	\$137.00	\$542.36
TIRES	\$756.70	\$80.00	\$836.70
TRANSFER CASE	\$141.40	\$164.40	\$305.80

Technician	Service Description				Parts	Labor	Job Total
TK	Comprehensive inspection of the vehicle's mechanical, electrical, safety, and overall condition to identify existing or potential issues before purchase. Includes visual inspection, fluid levels, brakes, suspension, steering, tires, leaks, engine/transmission operation, diagnostic scan, and road test. Findings are documented and reviewed with the customer.					274.00	274.00
TK	MANAGER NOTES: Check Engine Light and PSM Light on. Needs front Tires.					0.00	
TK	REPLACE ENGINE OIL SEPARATOR				1358.83	411.00	1769.83
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	WP-947605 OIL SEPARATOR	481.54	1	481.54			
N	WP-2372472 CRANKCASE VENT VALVE	583.32	1	583.32			
N	955 107 251 50 BREATHER HOSE	293.97	1	293.97			
	REPLACE BROKEN VACUUM LINES				297.86	685.00	982.86
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	948 110 668 56 TURBO CONTROL LINE	64.88	1	64.88			
N	948 110 666 71 VACUUM LINE	232.98	1	232.98			
TK	REPLACE SPARK PLUGS AND COILS				2236.96	602.80	2839.76
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	WP-945842 DIRECT IGNITION COIL	229.30	8	1834.40			
N	0 242 240 637 SPARK PLUG OE FINEWI	50.32	8	402.56			
TK	EURO SYNTHETIC OIL CHANGE FILL WITH FACTORY SPECIFIED QUALITY AND AMOUNT OF OIL-EURO FULL SYNTHETIC OIL TYPE: EURO SYNTHETIC.				405.36	137.00	542.36
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	WP-4275657 OIL FILTER KIT INSER	68.58	1	68.58			
N	15D934 CASTROL MTR OIL	168.39	2	336.78			
TK	PERFORM TRANSFER CASE SERVICE - BG: DRAIN & FILL TRANSFER CASE				141.40	164.40	305.80
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	79232 SYNCRO SHIFT II	56.56	2.5	141.40			
TK	REPLACE TIMING COVER BOLTS WITH STEEL BOLTS				72.72	822.00	894.72
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	WP-1333630 VALVE COVER BOLT	12.12	6	72.72			
	REPLACE ENGINE OIL COOLER GASKET				107.24	1096.00	1203.24
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
N	WP-558274 OIL COOLER GASKET	53.62	2	107.24			
	RESEAL LOWER ENGINE OIL PAN					1507.00	1507.00
TK	MOUNT & BALANCE TWO TIRES - Front 2				756.70	80.00	836.70
	<u>Part Number</u> <u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>			
S	WW WHEEL WEIGHT	5.99	2	11.98			
N	37205 295/35ZR-21 Michelin Pilot Sport Al	370.36	2	740.72			
	TIRE DISPOSAL	2.00	2	4.00			

Services Recommended to Customer

FRONT BRAKE PADS, RENEW Replace front disc brake pads, service
REAR DISC PADS, RENEW Replace rear disc brake pads, service



Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041463**9/14/2026
3:51 pm****2012 PORSCHE CAYENNE**

V8-4806 4.8L DOHC
VIN : WP1AC2A23CLA81147

Mileage :
Trans : AUTO
License :

COLR : BLUE
Unit # TURBO

DJPJ HOLDINGS

14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total
Parts Recommended To Customer				
1	WP-271531	BRAKE PAD SET		
2	WP-2181411	BRAKE PAD SENSOR-FRO		
2	WP-3258956	BRAKE PAD SENSOR-REA		
1	958698451C	PCCB REAR PAD SET		

Repair Order Notes

Itemized Fee Summary	Amount
TIRE DISPOSAL	\$4.00
(Fees are included in totals below)	

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ Date: _____

TOTAL PARTS	\$5,373.07
TOTAL LABOR	\$5,779.20
SUBLET	\$0.00
SHOP SUPPLY	\$201.25
SUBTOTAL	\$11,353.52
OTHER FEES	\$4.00
SALES TAX	\$376.27
INVOICE TOTAL	\$11,733.79
PAID	\$0.00
DUE	\$11,733.79

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

**Thank you for your business!**