

HWB CLEANING SERVICES LLC

COMMERCIAL PROPOSAL: BOSANNA LLC — 11-BUILDING COMMERCIAL PORTFOLIO

Client / Prime:	Bosanna LLC (Attn: Angelica Hudgins)	Proposal ID:	HWB-BID-2026-FW01 (v3.8.0)
End Client Portfolio:	Bosanna LLC (11 Landmark Buildings)	Effective Date:	September 04, 2026
Central Office:	425 Houston Street, Suite 250, Fort Worth, TX 76102	Dispatch Origin:	Arlington, TX
Primary Scope:	11 Ground-Floor Commercial Lobbies (11,153 Cleanable SF)	Subcontractor Role:	Specialized Floor Care Crew (2 Techs)

DATA INTEGRITY NOTICE (ISO 9001 Clause 8.2.2): Cleanable square footages are reconciled to on-site empirical field measurements (11,153 Cleanable SF).

EXECUTIVE SUMMARY: CLIENT NEEDS, GOALS & OUR PROPOSED PLAN

1. Current Situation & Needs: Bosanna LLC oversees facilities operations for its commercial portfolio across 11 landmark downtown buildings in Sundance Square. Heavy daily foot traffic, grit, and rain have dulled entrance lobbies, settling dirt into stone and grout pores. As specialized floor care subcontractor to Bosanna LLC, HWB ensures all lobbies project an immaculate first impression.

2. Client Goals: (1) Strip away old ground-in soil to reveal true floor condition and existing damage; (2) Seal stone and grout pores to prevent coffee, drink, and grease stains; (3) Set up a predictable maintenance routine (quarterly/semi-annual) within budget; (4) Ensure zero daytime tenant disruption.

3. Proposed 3-Phase Solution: (1) Phase 1 Deep Clean Reset (rotary machine scrub & edge extraction); (2) Phase 2 Sub-Surface Sealer (STONETECH® BulletProof® oil/water barrier); (3) Phase 3 Scheduled Care via Track A (Quarterly) or Track B (Semi-Annual) recurring programs.

 Bosanna LLC Subcontractor Direct Partnership Advantage: As a specialized floor care subcontractor to Bosanna LLC, HWB has applied a full 25% direct discount on square footage rates across all 11 properties—providing a direct 20¢ per sq. ft. discount on Phase 1 deep cleaning (lowering the rate from \$0.80 down to \$0.60/SF).

1.0 COMMERCIAL PRICING SCHEDULE: INITIAL RESET & RECURRING MAINTENANCE PROGRAMS

Item	Building Name	Address	Primary floor system	Cleanable Area (SQFT)	Phase 1 Rate (Per SF)	Phase 1 deep clean (expose damage to consider options)	Quarterly Rate (Per SF)	Track A: Quarterly (Every 3 Months)	Semi-Annual Rate (Per SF)	Track B: Semi-Annual (Every 6 Months)
1	Chase Bank Building	420 Throckmorton St	Polished Terrazzo	2,126	\$0.60	\$1,275.60	\$0.41	\$861.03	\$0.51	\$1,084.26
2	The Westbrook	425 Houston St	Polished Terrazzo	1,520	\$0.60	\$912.00	\$0.41	\$615.60	\$0.51	\$775.20
3	The Carnegie	421 W 3rd St	Polished Terrazzo	1,175	\$0.60	\$705.00	\$0.41	\$475.88	\$0.51	\$599.25
4	The Cassidy	407 Throckmorton St	Polished Terrazzo	1,134	\$0.60	\$680.40	\$0.41	\$459.27	\$0.51	\$578.34
5	Burk Burnett Building	500 Main St	Ceramic Mosaic Tile	1,108	\$0.60	\$664.80	\$0.41	\$448.74	\$0.51	\$565.08
6	Sanger Lofts	222 W 4th St	Polished Terrazzo	1,071	\$0.60	\$642.60	\$0.41	\$433.76	\$0.51	\$546.21
7	Petroleum Building	210 W 6th St	Polished Marble Tile	860	\$0.60	\$516.00	\$0.41	\$348.30	\$0.51	\$438.60
8	The Commerce Building	420 Commerce St	Terrazzo Tile	840	\$0.60	\$504.00	\$0.41	\$340.20	\$0.51	\$428.40
9	Virtuoso Building	505 Main St	Polished Marble Tile	560	\$0.60	\$360.00	\$0.41	\$243.00	\$0.51	\$306.00
10	Knights of Pythias Hall	109-110 E 3rd St	Ceramic Mosaic Tile	414	\$0.60	\$360.00	\$0.41	\$243.00	\$0.51	\$306.00
11	Plaza Hotel Building	303 Main St	Commercial Quarry Tile	345	\$0.60	\$360.00	\$0.41	\$243.00	\$0.51	\$306.00
GRAND TOTAL SQUARE FOOTAGE (11 Lobbies)				11,153 SQF	\$0.60 avg	\$6,980.40	\$0.405 avg	\$4,711.77	\$0.51 avg	\$5,933.34

HWB CLEANING SERVICES LLC COMMERCIAL PROPOSAL: BOSANNA LLC — 11-BUILDING COMMERCIAL PORTFOLIO			
Client / Prime:	Bosanna LLC (Attn: Angelica Hudgins)	Proposal ID:	HWB-BID-2026-FW01 (v3.8.0)
End Client Portfolio:	Bosanna LLC (11 Landmark Buildings)	Effective Date:	September 04, 2026
Central Office:	425 Houston Street, Suite 250, Fort Worth, TX 76102	Dispatch Origin:	Arlington, TX
Primary Scope:	11 Ground-Floor Commercial Lobbies (11,153 Cleanable SF)	Subcontractor Role:	Specialized Floor Care Crew (2 Techs)
DATA INTEGRITY NOTICE (ISO 9001 Clause 8.2.2): Cleanable square footages are reconciled to on-site empirical field measurements (11,153 Cleanable SF).			

2.0 ADDITIONAL CLIENT OPTIONS: PENETRATING SEALER, STAIRCARE, DIAMOND RESTORATION & ART HANDLING

Item	Building Name	Address	Primary floor system	Cleanable Area (SQFT)	Option A: Sealer (BulletProof®) \$0.2325 / SF	Option B: Stair Care (Unit Rate Add-On 500 Main St Only)* N/A (Excluded)	Option C: Capital Diamond Restoration (Restores Mirror Shine • Marble & Terrazzo Only) N/A (Exempt)	Option D: Furniture Handling (Hourly T&M)
1	Chase Bank Building	420 Throckmorton St	Polished Terrazzo	2,126	\$494.30	N/A (Excluded)	\$4,225.43	Available Per Hour
2	The Westbrook	425 Houston St	Polished Terrazzo	1,520	\$353.40	N/A (Excluded)	\$3,021.00	Available Per Hour
3	The Carnegie	421 W 3rd St	Polished Terrazzo	1,175	\$273.19	N/A (Excluded)	\$2,335.31	Available Per Hour
4	The Cassidy	407 Throckmorton St	Polished Terrazzo	1,134	\$263.66	N/A (Excluded)	\$2,253.83	Available Per Hour
5	Burk Burnett Building	500 Main St	Ceramic Mosaic Tile	1,108	\$257.61	\$3/Stp + \$21/Lnd	N/A (Exempt)	Available Per Hour
6	Sanger Lofts	222 W 4th St	Polished Terrazzo	1,071	\$249.01	N/A (Excluded)	\$2,128.61	Available Per Hour
7	Petroleum Building	210 W 6th St	Polished Marble Tile	860	\$199.95	N/A (Excluded)	\$1,709.25	Available Per Hour
8	The Commerce Building	420 Commerce St	Terrazzo Tile	840	\$195.30	N/A (Excluded)	\$1,669.50	Available Per Hour
9	Virtuoso Building	505 Main St	Polished Marble Tile	560	\$139.50	N/A (Excluded)	\$1,192.50	Available Per Hour
10	Knights of Pythias Hall	109-110 E 3rd St	Ceramic Mosaic Tile	414	\$139.50	N/A (Excluded)	N/A (Exempt)	Available Per Hour
11	Plaza Hotel Building	303 Main St	Commercial Quarry Tile	345	\$139.50	N/A (Excluded)	N/A (Exempt)	Available Per Hour
GRAND TOTAL SQUARE FOOTAGE (Additional Options)				11,153 SQF	\$2,704.91	Unit Rate Only	\$18,535.43	Available Per Hour

3.0 COMMERCIAL PROGRAM EXECUTIVE SUMMARY & BILLING TERMS

Service Phase / Scope Module	Scope of work	Rate Basis	Portfolio Invoiced Investment	Billing Frequency & Program Terms
Phase 1 deep clean (expose damage to consider options)	Rotary machine scrub, deep cleaning solution, edge hand scraping, and extraction across 11 lobbies (600 SF min baseline). Strips surface dirt down to bare floor to expose existing damage for mutual review; does not grind stone or remove scratches. Reflects 25% direct portfolio discount (20c/SF discount off \$0.80 regular rate).	\$0.60 / SF	\$6,980.40 complete	One-Time Baseline Service
Phase 2: Modular Sub-Surface Sealer (STONETECH® BulletProof®)	Deep penetrating sealer applied after cleaning into stone and grout lines (600 SF baseline). Repels water and oil spills; does not create a wax film or shine, and does not stop acid etch marks on polished marble. Reflects 25% direct portfolio discount (7.75c/SF discount off \$0.31 regular rate).	\$0.2325 / SF	\$2,704.90 complete	Post-Clean Protection (12–24 Month Lifecycle)
Phase 3 (Track A): Quarterly Maintenance (Recommended Program)	Recurring 90-day maintenance scrub across 8 Terrazzo/Marble lobbies; deep brush scrub and grout extraction across 3 Mosaic/Quarry lobbies (600 SF min). Routine cleaning only; does not include diamond grinding. Reflects 25% direct portfolio discount (13.5c/SF discount off \$0.54 regular rate).	\$0.405 / SF	\$4,711.77 / pass	Every 3 Months (4x / Year • Recommended)
Phase 3 (Track B): Every Six Months Deep Restorative Scrub	Intensive 180-day deep scrub, heavy cleaner dwell time, and machine extraction across 11 lobbies (600 SF min baseline). Removes 6 months of ground-in traffic dirt; does not include diamond grinding. Reflects 25% direct portfolio discount (17c/SF discount off \$0.68 regular rate).	\$0.51 / SF	\$5,933.34 / pass	Every 6 Months (2x / Year Semi-Annual)
Add-On Option B: Dedicated Marble Staircase Care (500 Main St Only)	Step machine scrub (\$3.00/step), riser wipe-down, brass nosing polish, landing deep clean (\$21.00/landing), and sealer at 500 Main St only. Billed strictly by actual step count on site; excludes repairs and other 10 buildings.	\$3/Stp + \$21/Lnd	Unit Rate Only (T&M Count)	Optional Per Service Pass (500 Main St Only)
Add-On Option C: Capital Diamond Restoration	Multi-step diamond grinding and polishing with wall protection across 8 stone lobbies (9,326 Billing SF). The only service that cuts out deep scratches and restores a high-gloss shine; ceramic and quarry tile are exempt. Reflects 25% direct portfolio discount (66.25c/SF discount off \$2.65 regular rate).	\$1.9875 / SF	\$18,535.43 complete	As-Needed Capital Project (8 Stone Lobbies)
Add-On Option D: Furniture & Artwork Handling	Building staff clears and replaces lobby furniture before and after service. Crew moving assistance is available upon written request on an hourly basis; HWB is not responsible for unmoved furniture.	Available Per Hour	Hourly T&M (Upon Request)	Client-Managed Default (Hourly Moving Option)

HWB CLEANING SERVICES LLC			
COMMERCIAL PROPOSAL: BOSANNA LLC — 11-BUILDING COMMERCIAL PORTFOLIO			
Client / Prime:	Bosanna LLC (Attn: Angelica Hudgins)	Proposal ID:	HWB-BID-2026-FW01 (v3.8.0)
End Client Portfolio:	Bosanna LLC (11 Landmark Buildings)	Effective Date:	September 04, 2026
Central Office:	425 Houston Street, Suite 250, Fort Worth, TX 76102	Dispatch Origin:	Arlington, TX
Primary Scope:	11 Ground-Floor Commercial Lobbies (11,153 Cleanable SF)	Subcontractor Role:	Specialized Floor Care Crew (2 Techs)
DATA INTEGRITY NOTICE (ISO 9001 Clause 8.2.2): Cleanable square footages are reconciled to on-site empirical field measurements (11,153 Cleanable SF).			

4.0 LOBBY FLOOR CONDITION: 4-POINT PHOTO INSPECTION

Photographic documentation of floor conditions, wear patterns, and recommended services across portfolio lobbies.

PHOTO 1: PLAZA HOTEL BUILDING (303 MAIN ST)



Primary floor system: Commercial Quarry Tile

Floor Issue: Chemical Bleach Stains & Deep Grout Soil Buildup

Condition Observed: Harsh cleaner or bleach stripped the tile finish (white patch); grease soaked into unsealed tile; heavy dirt along grout lines.

Recommended Service: Deep machine scrub to lift embedded soil (Phase 1) + Option A: BulletProof® Sealer to protect tile and grout from stains.

PHOTO 2: CHASE BANK BUILDING (420 THROCKMORTON ST)



Primary floor system: Polished Terrazzo

Floor Issue: Heavy Traffic Wear Pattern & Loss of Floor Shine

Condition Observed: Heavy foot traffic wore away surface shine along center walkway; fine scratches now trap dirt and leave floors looking dull.

Recommended Service: Regular quarterly machine scrub (\$0.405/SF) to remove gritty soil and keep floors clean; deep gouges require Option C: Diamond Restoration.

PHOTO 3: PETROLEUM BUILDING (210 W 6TH ST)



Primary floor system: Polished Marble Tile

Floor Issue: Acid Stain Marks & Chemical Etch Rings

Condition Observed: Acidic spills (coffee, citrus drinks, sanitizer drips) ate into polished marble, leaving dull, rough white spots that mopping cannot clean.

Recommended Service: Diamond polishing to smooth out etch marks and restore shine + Option A: BulletProof® Sealer to protect against stains.

PHOTO 4: VIRTUOSO BUILDING (505 MAIN ST / SCHWARZ BLDG)



Primary floor system: Polished Marble Tile

Floor Issue: Deep Gouges & Scratches from Moving Equipment

Condition Observed: Heavy equipment, freight carts, or unpadded furniture dragged across floor cut deep white scratches into the black marble.

Recommended Service: Option C: Diamond Restoration (\$1.9875/SF) to grind out deep scratch valleys and polish back to a high-gloss finish.