Notice of Violation of IEEE Publication Principles

"New Distribution Class Arrester Ground Lead Disconnector Design,"

by Yong-Sung Choi; Ju-Ho Yun; Hyang-Kon Kim; Chung-Seog Choi; Kyung-Sup Lee, in the Proceedings of the 2008 International Conference on Condition Monitoring and Diagnosis, 21-24 April 2008, pp 731-734

After careful and considered review of the content and authorship of this paper by a duly constituted expert committee, this paper has been found to be in violation of IEEE's Publication Principles.

This paper is a near duplication of the original text from the papers cited below. The original text was copied without attribution and without permission.

Due to the nature of this violation, reasonable effort should be made to remove all past references to this paper, and future references should be made to the following articles:

"New Distribution Class Arrester Ground Lead Disconnector Design Enhances Detonation Reliability and Improves Arrester Performance," by Lenk, D.W,

in the Proceedings of the 2004 Power Systems Conference and Exposition, 10-13 Oct. 2004, vol. 3, pp. 1397-1406

New Distribution Class Arrester Ground Lead Disconnector Design

Yong-Sung Choi^{1*}, Ju-Ho Yun¹, Hyang-Kon Kim², Chung-Seog Choi² and Kyung-Sup Lee¹

Department of Electrical Engineering, Dongshin University, 252 DaeHo-dong, Naju 520-714, Korea

Electrical Safety Research Institute

*E-mail: yschoi67@dsu.ac.kr

Abstract--This paper examines performance characteristics of existing distribution class arrester ground lead disconnecting devices. The paper also introduces a new Distribution Class ground lead disconnector design that not only extends the claimable detonation range well below the 20 amps specified in industry standards, but is very durable when exposed to severe arrester durability tests. Finally, this paper shows how this next generation disconnector interacts with the connected arrester to improve the overvoltage withstand capability of the arrester assembly.

Index Terms--Disconnector, Distribution class arrestor, Metal Oxide varistor, Polymer-housed design, Reliability

I. INTRODUCTION

Electric utility operating system reliability has been identified as a critical parameter of the utility performance. For distribution systems, one factor that can affect system reliability is the failure rate of surge arresters. A related factor is the consistency of operation of the arrester ground lead disconnector in the unlikely event of an arrester failure. This paper examines performance characteristics of existing distribution class arrester ground lead disconnecting devices.

In particular, it will focus on how the detonator performs after the series connected arrester fails, under various system conditions. The paper also introduces a new disconnector design that not only extends the claimable detonation range well below the 20 amps specified in industry standards, but is very durable when exposed to severe arrester durability tests. It will also be shown how this device interacts with the connected arrester to improve the overvoltage withstand capability of the arrester assembly.

It has been standard practice to protect distribution class equipment, particularly pole top transformers, with distribution class arresters. Protection of the dielectric integrity of the transformer is provided by the closely connected arrester. Approximately twenty years ago, the traditional gapped-silicon carbide distribution class arrester design was replaced by the improved gapless arrester, based on metal oxide varistor (MOV) technology. In addition to performance improvements associated with this new MOV technology, the traditional porcelain-housed arresters were replaced during this same time period by polymer-housed arresters.

This work was finally supported by MOCIE program (R-2007-2-234-01).

Conversion to MOV resulted in lowering of the protective levels of the arrester, particularly under fast front rate of rise surges, providing improved protection to the internal insulation of the transformer. Implementation of polymer housings significantly improved the performance of the arrester in the unlikely event of arrester failure. Specifically, the polymer housed arrester removed the concern of violent porcelain fragmentation associated with porcelain-housed distribution class arresters. To validate this characteristic, the IEEE C62.11 Standard instituted a short circuit test for polymer-housed arresters. The predecessor porcelain-housed distribution class arrester had no required short circuit performance requirement.

Conversion from porcelain to polymer-housed distribution class arresters allowed manufacturers to reduce the active element length of their arrester designs. The porcelain designs traditionally had a ground lead disconnector attached to the base end of the arrester and the arrester was supported by a grounded metal "bellyband" bracket, typically attached around the porcelain housing approximately one-third the distance from the bottom end of the arrester housing. The distance from the top edge of the metal bellyband to the arrester top end cap provided the required line to ground insulation clearance as specified for each arrester rating in the C62.11 Standard. The distance from the bottom of the grounded bellyband to the ground lead disconnector provided the necessary clearance to prevent the intact, failed porcelain arrester from locking out the system if the arrester should fail but remain intact.

For the polymer-housed designs, this "lockout prevention" clearance was relocated to the supporting bracket, which typically attaches to the base end of the polymer-housed arrester. Because this member now has the added requirement of voltage withstand after arrester failure, its composition changed from metal to an insulating plastic material. Should the polymer-housed arrester fail and remain intact (typical), the ground lead disconnector, connected between the base of the arrester and the arrester ground lead, will detonate.

Disconnection of the ground lead causes the base end of the failed (intact) arrester to assume system line potential. The composition and shed design of the insulated bracket allows the arrester location to remain energized until the utility operating personnel replace the failed arrester. The above description is valid, assuming that the ground lead disconnector reliably detonates during arrester failure. Should the disconnector fail to operate, the base end of the failed arrester will remain connected to system ground and the line will lock out until upstream protection operates and the failed arrester is replaced.

II. DISCONNECTOR DESIGN

There are two basic detonator designs used in disconnectors currently being manufactured. As noted earlier, virtually all designs attach the isolator to the ground end of the arrester. One design mounts the arrester base end on an insulating bracket and holds the arrester to the bracket by attaching a disconnector to the underside of the assembly. This design was a carryover from porcelain arresters. The second design, targeted specifically to polymer arresters, integrates the disconnector into the body of the insulating bracket. This integrated designs attaches to the base end of the arrester.

Regardless of which approach is utilized, both designs use the same basic internal design approach. An unprimed cartridge is used to promote separation of the disconnector. This cartridge is typically located in the vicinity of a sparkgap, which is oriented in parallel with some type of electrical grading component. Manufacturers have utilized a variety of components, including electronic grading electronic resistors, conductive polymers, and higher wattage resistors. Figure 1 shows an electrical schematic of a typical ground lead disconnector. The sparkgap, located electrically in parallel with the resistor, provides a bypass function when the arrester assembly is subjected to abnormal surge duty. Voltage drop across the grading component during this abnormal surge duty causes the bypass gap to sparkover. For required arrester durability tests defined in the standard, the arrester is expected to withstand the duty without failing and the detonator is expected to withstand the duty without detonating.




Fig. 1. Electrical schematic of ground lead disconnector.

The thermal design of the disconnector is such that there is not sufficient coulomb content in the sparkgap region to cause the adjacent cartridge to detonate during arrester durability tests. However, if the surge duty is sufficient to cause the arrester to fail, the subsequent flow of system fault current available at the arrester location is intended to provide sufficient heating of the cartridge to cause it to detonate. The design of the disconnector is such that this detonation then causes the ground lead to be separated from the base end of the arrester.

III. RESULTS AND DISCUSSIONON

A. Disconnector Detonation curve

As noted, the disconnector current detonation range specified in the standard is 20 to 800 amps. The standard does not specify the shape of the currenttime detonation curve. It merely defines the procedure for performing the test on new disconnectors. Above 800 amps, all designs should detonate very quickly from the high heat associated with the high 60 Hz fault current. Problems can be encountered on arresters applied to non-effectively grounded systems or on arresters located on weak feeders where only low fault currents are available (<20amps). Specifically, the cartridge relies on heating from the system 60 Hz fault current to cause detonation.

Inherent in these weak source current locations is the possibility that the cartridge is not heated sufficiently by the available 60 Hz current to detonate before upstream protection triggers. Reliable detonation of the disconnector under this weak source condition is an issue of concern. Figure 2 shows disconnectors tested per the current.




Fig. 2. Comparison of detonation curves for various domestically produced resistor-graded disconnectors.

B. Durability of capacitor-graded disconnector

As shown above, the new capacitorgraded disconnector will detonate down to 1 ampere. As the design becomes more sensitive to low current detonation, there is a concern that the disconnector might become too sensitive and detonate on required arrester durability tests. Section 8.18.2 of IEEE C62.11-1999 standard defines required design tests.

To address this concern, the following durability tests were performed. Five arresters with capacitor-graded insulating brackets were subjected to (18) shots of 400 amp, 2ms duration, exceeding the 18 shot, 250 amp test requirement for Heavy Duty Distribution Class arresters. While not detonating as a result of the repetitive duty, all five disconnectors detonated when subjected to a 1 amp fault current.

Six capacitor-graded disconnectors were also subjected to (2) 100 kA 5.5/12 discharges with no detonation occurring. In addition, the measured capacitance changed less than 5% and there was nopartial discharge measured as a result of this severe duty. As a final confirmation of the electrical integrity, three disconnectors that successfully passed the (2) 100 kA

shots were tested for detonation in a 6-amp test circuit. Time to detonation on these three samples was .983, 1.0, and 1.43 seconds, well within the claimed detonation curve for the new disconnector.

C. Examination of Performance of Resistor-Graded Disconnector Designs in the Domestic Marketplace After Exposure to Arrester Durability Tests

A limited number of disconnector designs currently in the marketplace were subjected to (2) 100 kA 4/10 current discharges. Design A successfully withstood the (2) shot test without detonating. Design B had the disconnector detonate on the first 100 kA surge on both samples tested. A third sample withstood two discharges without detonation. Three disconnectors of design C and design D successfully withstood (2) 100 kA discharges without detonation. Design A disconnectors were then subjected to a 20-amp and a 5-amp detonation tests. At 20-amp, detonation occurred. At 5-amp, there was no detonation. The third sample of design B did not detonate at 20-amps while two did not detonate at 5-amps. Design D detonated at both 5 and 20 amps.

D. Arrester-Disconnector Interaction Issues

The impedance of the capacitor-graded isolator is significantly higher than that of the existing domestic resistor-graded disconnector designs. This has a significant impact on the voltage sharing that exists between the connected arrester metal oxide disc elements and the series connected disconnector. Figure 3 displays the 60 Hz voltage measured across the disconnector as a function of total voltage applied to the arrester-disconnector combination. Note that below 1.25 per unit MCOV, the disconnector develops less than 1 kV across the grading capacitor, well below the continuous AC capability of the device.




Fig. 3. Voltage across capacitor-graded bracket as function of applied voltage PU MCOV for HD distribution arrester ratings.

E. Arrester Temporary Overvoltage Improvement Associated With Capacitor-Graded Disconnector

It should be pointed out that most manufacturers publish only one TOV curve for their distribution arrester designs. This curve is typically based on the TOV capability of the arrester only, since Distribution Class arresters can be installed without insulating brackets and ground lead disconnectors. The actual arrester assembly (including disconnector) TOV capability may exceed that claimed for the arrester alone. Figure 4 shows a typical gapless distribution

class arrester temporary overvoltage curve.




Fig. 4. Typical no prior duty TOV curve for gapless distribution arrester.

As noted previously, the significantly higher impedance of the capacitorgraded disconnector electrically interacts with the capacitive and non-linear resistance characteristic of the metal oxide discs. At system operating voltage levels, the voltage across the capacitively graded disconnector is typically a few hundred volts, compared with tens of volts for the resistively graded disconnector. As applied voltage increases above operating levels, the parallel combination of the disconnector capacitor and its sparkgap assume a higher percentage of total voltage than does the resistively graded disconnector. Because the capacitor does not experience I²R loss, in contrast to the resistance graded design, the disconnector can withstand overvoltages for extended periods of time, as long as the capacitor voltage does not exceed the bypass gap sparkover level. Unlike an arrester with a resistively graded disconnector, which has a claimed TOV capability that is independent of arrester voltage rating, arresters with capacitively graded disconnectors have a rating-dependent TOV curve.

IV. CONCLUSION

Introduction of a high voltage capacitorgraded arrester ground lead disconnector addresses utility concerns regarding reliable detonation of the Distribution Class arrester disconnector. Test data confirms the detonation integrity of the disconnector is maintained even after the arrester is subjected to high current surge duty prevalent in the distribution system environment. Even under weak source temporary overvoltage conditions, which can damage the resistance-graded design affecting detonation reliability, the capacitor-graded design performs properly. The detonation range of this design has also been reliably extended to 1 amp, below the 20 amps required by the arrester design standard.

Finally, the interaction of the disconnector grading capacitor with the series-connected arrester metal oxide disc elements actually improves the arrester assembly temporary overvoltage withstand capability, making the design less vulnerable to TOV failures. Since the vast majority of distribution class arresters are sold domestically with ground lead disconnectors, this design improvement in the disconnector to improve detonation reliability also translates into a significantly improved distribution class arrester design.

V. REFERENCES

- [1] IEEE Standard for Metal-Oxide Surge Arresters for AC Power Circuits (>1 kV) IEEE Std C62.11, 1999.
- [2] CEI IEC 60099-4 (2001-12) Ed. 1.2 Consolidated Edition: Surge Arresters-Part 4: Metal Oxide Surge arresters Without Gaps for AC Systems.

 IEEE Guide for the Application of Metal-Oxide Surge Arresters for
- Alternating-Current Systems IEEE Std C62.22, 1997.