

The cost of each unit of work

Unit = one normal 16×16 weight-tile pass (a sparse tile does two) · the grid's cost halves; the processor's grows with the position notes

■ Berkeley original ■ Ours, 2:4 ■ Ours, 4:8

