

World Leader in Testing Services for the Medical Device Industry

2261 Tracy Road Northwood, OH 43619 Phone 419-666-9459 Fax 419-666-2954

Master Bond, Inc. 154 Hobart Street Hackensack, NJ 07601 Attn: DR. WALTER BRENNER LAB NO. 91T-09579-00 P.O. NO. 06021091

ID NO. Not Supplied

CERTIFICATE OF COMPLIANCE

USP BIOLOGICAL TESTS CLASSIFICATION VI

Test Article: Epoxy System EP30Med

ACUTE SYSTEMIC TOXICITY (USP): The saline, alcohol in saline, polyethylene glycol 400 and cottonseed oil extracts of the test article injected into mice did not produce a significantly greater systemic reaction than the blank extractant.

<u>INTRACUTANEOUS TOXICITY (USP)</u>: The saline, alcohol in saline, polyethylene glycol 400 and cottonseed oil extracts of the test article injected intracutaneously in rabbits did not produce a significantly greater tissue reaction than the blank extractant.

<u>IMPLANTATION TEST (USP)</u>: The macroscopic reaction of the test article implanted 7 days was not significant as compared to the USP Negative control plastic.

The sample of test article extracted at a ratio of 60 sq. cm/20 ml and at a temperature of 50°C for 72 hour(s) met the requirements of a USP Class VI Plastic.