LAB 3 VENIFICATION W2024

| SI OPERATION | | | MAN- Try |
|---|--|---|------------------|
| 1) REGULATOR (2) BATTERY VOLT 3) POWER TO AND | TO L293D (YEL)] | 1 10 00 0 | 7 |
| * USE BENCH SUPPLE SET TO 8.0 YOU TOP AND BOTTOM CHASSII INSTALLED. | S BOTH REA | NT 356 | 185 0 |
| * ONE DOCUMENT TO B.S. | FRONT FRONT OIN 30 IA DIN 31 24 ARDOINO PINS, | EN 3 3,4 MOT OIN 37 34 2 OIR 33 4A FI | |
| * REVIEW [] RUBIUC MOT 3 RL | EN 5 1,2 DIR 34 1A DIR 35 2A | EN 6 3,4 MODE 36 3 A 4 POIN 36 37 4A R | R |
| | | | V \ FEB 1 3 2024 |

Huruy Huruy section 021

Lab 3 Wiring instructions

Motor wiring colours and pin numbers

| Motor 1 | | Motor 2 | | Motor 3 | | Motor 4 | | | | | |
|--------------|--------------|--------------|--------------|--------------|--------|--------------|--------|---------------------|------------------|--------|-----------|
| L293D right | | L293D right | | L293D left | | L293D left | | | | | |
| Pos pin = 6 | | | Pos pin = 1 | Neg 1 pin | = 14 | Pos pin = 6 | _ | eg n = 3 | Pos [pin = 1 | _ | g = 14 |
| Arduino pins | | Arduino pins | | Arduino pins | | Arduino pins | | | | | |
| Pin= 2 | Pin=30 [] | Pin=31 | Pin= 3 [] | Pin=32 | Pin=33 | Pin= 5 | Pin=34 | Pin=35 | Pin= 6 [] | Pin=36 | Pin=37 |
| L293D right | | L293D right | | L293D left | | L293D left | | | | | |
| Pin= 1 | Pin=2 | Pin=7 | Pin=9 | Pin=10 | Pin=15 | Pin= 1 | Pin=2 | Pin=7 | Pin=9 | Pin=10 | Pin=15 |