10728

MAIN FUSE SWITCH (MFS)
L1. 1L1
L2. 1L2
L3. 1L3
N. NN

VOLTMETER FUSES & NEUTRAL LINK (VF & VNL)

VOLTMETER SELECTOR SWITCH (VSS)

VOLTMETER

CONTROL SUPPLY SWITCHFUSE.

C/O SWITCH

CT1 SF1 SF2 CT2

MF ISOLATOR IS NL
A. B. C. NN.
MOTORISED HOIST STARTER FEEDER
TERMS—100.101.102.103.
MCC 5B FEEDER
TERMS—104.105.106.107.

MF IS NL
A. NN.
M°546 STARTER FEEDER
TERMS—108.109.

MF E.L.R. EARTH LEAKAGE RELAY
EARTH LEAKAGE TRANSFORMER E.L.C.T.
OVERLOAD CURRENT TRANSFORMER O.L.C.T.
OVERLOAD O.L.
AMMETER CURRENT TRANSFORMER A.C.T.
AMMETER
I.S.
MAIN CONTACTOR M.C.
A. B. C.
POWER FACTOR CORRECTION CAPACITORS

CP (CCP) — CONTROL POWER RELAY 2.20.
PILOT RELAY 8.17.18. 4.6.
TIMER 4
MAIN CONTACTOR 12.13.
SLAVE RELAY 15.16.17.18.
ISOLATOR RELAY 4.7.
HOUR COUNT:
RUNNING
STOPPED
PRESSURE SWITCH RELAY 3.19.
RESET P.B.
HAND IND.
TEST IND.
RUN IND.
STOP IND.
CHUTE BLOCKAGE IND.
TO DESK
TO MCC3B TH1
TH2
TH3
TH4
TO MCC 5B
D5-6 JTX 361V/11
1—37
LORRY LOADING CHAIN CONVEYOR LLCC1

FROM MCC 2C
FROM MCC 5B
PILOT RELAY 27.36.37
TIMER 23.
MAIN CONTACTOR 3.25.31.32.
SLAVE RELAY 23.
ISOLATOR RELAY 23.26.
HOUR COUNT:
RUNNING
STOPPED
PRESSURE SWITCH RELAY 22.38
RESET P.B.
HAND INDICATION
TEST
RUN
STOP
CHUTE BLOCKAGE INDICATION
TO DESK
D7-8 JTX 361V/21
41-61
LORRY LOADING CHAIN CONVEYOR LLCC3

LORRY LOADING CHAIN CONVEYOR LLCC1
TERMS 112.113A.114.

LORRY LOADING CHAIN CONVEYOR LLCC3
TERMS 115.116A.117.

NOTE :—
▲—DENOTES CONTACTS MADE IN 'ON' & 'TEST' POSITIONS
*— " " " " 'TEST' POSITION ONLY
†— " " " " 'ON' POSITION ONLY

10728

SCHEME FOR MCC 5A
SEAFORTH GRAIN TERMINAL
(34)

ISSUE 1 2 3

CTX 361 AD

DEWHURST & PARTNER LTD
MELBOURNE WORKS HOUNSLOW

TITLE— SCHEME FOR MCC 5A — SEAFORTH GRAIN TERMINAL

REVISION 3 Line14:R2 contact & reset P.B. added Line 33:R4 contact & reset P.B. added 16-7-81 R.H.N.
REVISION 2 R1 & R2 WERE ACROSS MAIN CONT; COILS 27-5-71
REVISION 1 LLCC1. SUSTAINING CONTACTS WERE ON M.C. 20-4-71

DRAWN BY
DATE 16-3-71
CHECKED BY
APPROVED BY
DATE

KEY.DIA.N°
EXT.DIA.N° RTX 361 AD
REL.DIA.N°
PANEL LAYOUT. GTX 361AD

CTX 361 AD