


RUN RELAY
 FEED VALVE OPEN RELAY
 FEED VALVE OPEN CONTACTOR
 DUMP VALVE OPEN RELAY
 DUMP VALVE OPEN CONTACTOR
 FEED VALVE CLOSE CONTACTOR
 DUMP VALVE CLOSE CONTACTOR
 EMERGENCY STOP RELAY
 LIMIT RELAY NO. 1
 LIMIT RELAY NO. 2



FEED VALVE MOTOR

DUMP VALVE MOTOR

RAIL LOADING PANEL

ISSUE 1 2 3 4 5

BTY36IBA

BTY36IBA

DEWHURST & PARTNER LTD.

MELBOURNE WORKS

HOUNSLOW

REVISION: 2
 OVERLOAD TRIPPED
 LAMPS FEED
 MODIFIED.

ORIGIN: EIS P
 21/1/71 SGD. JT

REVISION: 1
 MINOR MODS.

ORIGIN: EIP
 4/2/71 SGD. JT

REVISION: 4
 HEATER FUSE ADDED
 WIRING MOD TO SUIT
 DESK TERMS ADDED.
 ORIGIN: ICD
 9/2/72 JS

REVISION: 3
 LR2 CONTACT
 ADDED.
 ORIGIN: ICD
 16/12/71 JT

DRAWN BY: J.S.
 DATE: 23.11.70
 CHECKED BY:
 APPROVED BY:
 DATE:

THE DESIGN AND MANUFACTURING
 INFORMATION CONTAINED IN
 THIS DRAWING IS THE EXCLUSIVE
 RIGHT OF DEWHURST & PARTNER
 LTD AND MUST NOT BE COPIED
 OR USED FOR MANUFACTURING
 PURPOSES

KEY DAG No:
 EXT DAG No:
 REL DAG No: QTY 36 BA
 PANEL LAYOUT No: ETY 36 BA