

INCOMING SUPPLY
3300V 3 PHASE 50 HZ

1. CONNECTIONS 'A' TO BE 1260.40 DS.6105/4D BLACK CABLE (56411/128)
2. ALL OTHER CONNECTIONS TO BE 3210.20 DS.6231/B BLACK CABLE (56010/220)
3. THE WIRING ON ALL DEVICES MUST BE SUCH THAT THE CABLE HAVING THE LOWEST CONTROL NO. MUST BE WIRED TO THE TOP OR L.H. TERMINAL LOOKING AT THE FRONT OF THE DEVICE
4. STROKE NOS. 2, 3, & 4 SHOW SEQUENCE OF WIRING AND SHOULD APPEAR ON EQUIPMENT
5. LETTERS IN BRACKETS E.G. (A) DENOTE PLUG NOS. TO BE WIRED TO
6. FOR WIRING FROM SOCKET TERMINALS SEE DRG. X3052470
7. FOR HMC 400 TEST LINK SEE DRG. X3054250

BUSBAR RATING: 1200 AMPS

TITLE CONNECTION DIAGRAM FOR HMC400
3300 V 50 HZ STARTER
CONTROL BOARDS MCC4A4B

DRG. No. X3119326

REVISIONS		REVISIONS	
DATE 15-8-72	B	DATE 24-11-70	REV. 1
APPD		APPD	WATSON
ADD ECONO KESIK, FOR L.S. CONTR.		modi per Customhouse letter 12-11-70	
G.T.YE			

PAGE 4 LEG. 2 (FOR MCC 4A) LEG. 4 (" " 4B)	DATE 21-12-70	REV.
	APP'D	2
	WIRING STROKE N°S AND POSITION 2 TERM. AREAS ADDED.	
	DATE 6-1-71	REV.
	APP'D	3

Y AS STAGE 3)

TERMINAL INSCRIPTION
ON STALLING RELAYS
SR1 & SR2 HAVE BEEN
CHANGED.

DATE 31-3-71 REV.
APP'D JAT:el:1 1

CTE & CTE TABS GO
NEVER SHOWN & USED
BOY - AMMETER SCALE
IS NOW 0-20000

SYMBOL	DESCRIPTION
A	AMMETER
C	CONTACTOR (VIBRAD 300)
CB	CROUSE HOLE RELAY
CE	CAPACITANCE BALANCE TRANSFORMER
CP	CONTACTOR PILOT RELAY
CT	CURRENT TRANSFORMER
CVT	CONTROL VOLTAGE TRANSFORMER
E	EARTH
EFWS	EARTHING SWITCH
ELR	EARTH LEAKAGE RELAY
ESW	EARTH LEAKAGE SWITCH
ELT	EARTH LEAKAGE TRIP RELAY (LATCHED)
F	FUSE
HRC	HOURS RUN COUNTER
IS	MAIN ISOLATOR (600A LOAD BREAK)
ISOL	ISOLATOR (400 AMP OFF LOAD)
IR	INTERLOCK RELAY
LK	LINK
MI	MECHANICAL INTERLOCK
OL	OVERLOAD RELAY
OLT	OVERLOAD TRIP RELAY (LATCHED)
PMW	PUSH THE STARTER
PB	PUSH BUTTON
PPSW	PRESSURE PAD SWITCH
RTR	REMOTE TRIP RELAY
R	RELAY
RS	REMOTE SIGNAL
SL	SIGNAL LAMP
SRS	SEALING SWITCH
SR	STALLING RELAY (STAGE 3)
SRA	STALLING RELAY (STAGE 4)
TRA	TIMING AUXILIARY RELAY
TR	TIMING RELAY
V	VOLTMETER
W	RECTIFIER
USS	UNDER SPEED SWITCH W
RES	ECONOMY RESISTOR

21-6-71	REV	DATE: 19-6-71	REV	DATE: 3.5.71	REV
APP'D: R.F.	7	APP'D: D. M. 28	6	APP'D: R. M. 19	5
REMOTE WIRE 'S 532 SWITTLER & 532 SWITTLER		SSI TEST NORMAL SWITTLER WIRED TO REMOTE TERMINALS 1 & 2 27		SCOT (HARVEY WOOD) PROD IN POSITION 2 4 BUT INTENSIFY CHANNEL 1000 SUGET No. 3 (HARVEY)	

— TERMINAL ARRG1 FOR POSITION 2

COPYRIGHT AND CONFIDENTIAL

GEC-ELLIOTT INDUSTRIAL CONTROLS LTD
CONTROL GEAR ENGINEERING DEPT.

RUGBY, ENGLAND.
FOR DEWHURST & PARTNER LTD (READING) B342289

FAST ORDER No. 01-123401	DRG. No. X 3119326
-----------------------------	-----------------------

SHEET SIZE	20 x 30	THIRD ANGLE PROJECTION
---------------	---------	------------------------

STAGE (POSITION)	RATING HP	PLC AMPs	F ₁ F ₂ MAIN PIPE SIZE (AMPs)	AMMETER SCALE	CT ₁		CT ₁ CT ₂		OL (Mn2)		CT ₃ CT ₆	
					RATIO	FINAL RATIO	RATIO (TAP)	FINAL RATIO	% TAP		RATIO (TAP)	FINAL RATIO
1	600A	600	FAULT	MAKING	LOAD	BREAKING	ISOLATING	SWITCH	WITH	EARTH	SWITCH	
2	METERING	PANEL										
3	350	58	150	0-80A	300/1	8 SPASSES = 60/1	60/1	8 SPASSES = 60/1	100	80/1	1 PASS = 80/1	
4	350	58	150	0-80A	300/1	8 SPASSES = 60/1	60/1	8 SPASSES = 60/1	100	80/1	1 PASS = 80/1	

3	5-8-71	JHT
4	4-6-71	JHT
4	3-5-71	JHT
4	31-3-71	JHT
4	23-4-70	JHT

SEE OUTLINE DRG. X 3119325

0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
TERMINAL ARRANGEMENT FOR EACH STARTER (STAGE 3 & 4)
VIEWED FROM BACK OF CURBIE

DD	DDN	DATE
----	-----	------

2-JHT-2/10/75