5.6

10850

REVISION : 13
LINE 86 - SLOW SPEED PROXIMITY SWITCH ADDED.
TRIPPER No 8 ONLY
10-5-88 E.B.P.

REVISION : 12
[illegible]
ORIGIN: ICD
24/4/78 A.L.J.B

REVISION : 11
[illegible]
ORIGIN: ICD
16/3/78 A.L.J.B

REVISION : 10
[illegible]
ORIGIN: ICD
3/3/78 A.L.J.B

REVISION : 9
[illegible]
ORIGIN: ICD
16/12/77 A.L.J.B

REVISION : 8
[illegible]
ORIGIN: ICD
A.L.J.B

REVISION : 7
[illegible]
ORIGIN: (SITE)
SGD. A.L.J.B

REVISION : 6
NO 'ASY' CONTACT ADDED [illegible]
ORIGIN: ICD
30/8/77 SGD A.L.J.B

REVISION : 5
MINOR MODS + INTERLOCKS TO THE SCRAPERS
ORIGIN : ICD
4/8/77 SGD. A.L.J.B

REVISION : 4
OVERSPEED LAMP & CABLE REELING CORES [illegible] ADDED
TRIPPER & SCP [illegible]
ORIGIN : ICD
19/7/77 SGD. A.L.J.B

REVISION : 3
RELAY 8LGVI ADDED,
PANEL STOPLOCKS [illegible]
& MINOR MODS.
ORIGIN : ICD
/7/77 SGD. A.L.J.B

REVISION : 2
MINOR MODS ADDED.
ORIGIN : ICD
2/6/77 SGD A.L.J.B

REVISION : 1
GRAIN FLOW TIMER CIRCUIT MODIFIED.
ORIGIN
2/ SGD. A.M

DRAWN BY A.M.
DATE 9.12.76
CHECKED BY
APPROVED BY
DATE 5.1.77

KEY DIAG. No.
EXT. DIAG. No.
REL. DIAG. No.
PANEL LAYOUT No.

THE DESIGN AND MANUFACTURING INFORMATION CONTAINED IN THIS DRAWING IS THE EXCLUSIVE RIGHT OF DEWHURST & PARTNER LTD. AND MUST NOT BE COPIED OR USED FOR MANUFACTURING PURPOSES.

ISSUE 1 2 3 4 5 6 7 8 9 10 13

DTX361DC

DEWHURST & PARTNER LTD.
MELBOURNE WORKS HOUNSLOW

TITLE: TRIPPER Nos 8 & CONTROL CIRCUITS

DTX361DC