10900

REVISION : 18	REVISION : 17	REVISION : 16	REVISION : 15	REVISION : 14
N/O DFC CONTACT MOVED ON LINE 324 RELAY DP13 RT ADDED LINE 323 N/C G1R & G2R CONTACTS ADDED ON LINE 312	DFC CONTACT ON LINE 300 REPLACED BY PR CONTACT DFC CONTACT ON LINE 313 REPLACED BY PR CONTACT. + SLAVE RELAYS	TERMINALS G2-73X, G2-?, ? & G2-?X ADDED. + CONTACTS & WIRE No's	CONTACT No. ADDED ON L415.	REDRAWN
ORIGIN : ICD 12/4/78 SGD. A.L.J.B	ORIGIN : ICD 14/11/77 SGD. A.L.J.B	ORIGIN : ICD 13/7/77 SGD. A.L.J.B	ORIGIN : ICD 1/7/77 SGD. A.L.J.B	ORIGIN : ICD 21/4/77 SGD. Briggs

REVISION 20
Dust plant sequenced shut down—Mods on lines 202,228,253,
21-6-77

REVISION : 19
G1R & G2R CONTACTS WERE ON LINE 312. ANOTHER CONTACT ON DP13 RT USED.
ORIGIN: ICD
8/8/78 A.L.J.B

DRAWN BY	A.M.
DATE	26/1/70
CHECKED BY	
APPROVED BY	
DATE	

THE DESIGN AND MANUFACTURING INFORMATION CONTAINED IN THIS DRAWING IS THE EXCLUSIVE RIGHT OF DEWHURST & PARTNER LTD. AND MUST NOT BE COPIED OR USED FOR MANUFACTURING PURPOSES.

KEY DIAG. No.	
EXT. DIAG. No.	STX 361 Y
REL. DIAG. No.	
PANEL LAYOUT No.	HTX 361Y

ISSUE ~~15~~ ~~16~~ ~~17~~ ~~18~~ ~~19~~ ~~20~~ 21

DTX 361 Y / 2

DEWHURST & PARTNER LTD.
MELBOURNE WORKS HOUNSLOW

TITLE:
SCHEME FOR MCC 2C - SEAFORTH GRAIN TERMINAL

DTX 361 Y / 2

GAF 1868/74