## IT'S THE LAW...

PLEASE FOLLOW ALL WORKPLACE SAFETY GUIDELINES!



 ALWAYS wear safety glasses at all times when conducting business on machining floor. Safety glasses protect your eyes from flying debris.



 ALWAYS wear cut resistant gloves when handling objects on machining floor. Gloves help protect hands from sharp and rough objects.



 <u>ALWAYS</u> wear steel-toe work boots when on facility premises. Steel-toe boots help protect your feet from potential blunt force trauma.