
Production success during training, every stage on the same scale
A - 2 fixed points
B - 3 fixed points (v1)
B3 - 3 fixed points (v2)
R3 - 3 random points (deployed)
R4 - + end-range rule
R5 - + speed cost (quadratic)
R6 - + speed cost (linear+quad)
F2 - 2 points, free order
F3 - 3 points, free order
100%
80%
60%
40%
20%
0%
0
200K
400K
600K
800K
1.0M
blue = mean of seeds, grey = individual seeds; x-axis = environment steps