
Speed against accuracy: the speed cost bought human speed with reliability
small dots = seeds, diamonds = stage mean
human range
R3
R4
R5
R6
R3 - 3 random points (deployed)
R4 - + end-range rule
R5 - + speed cost (quadratic)
R6 - + speed cost (linear+quad)
final success
100%
80%
60%
40%
20%
0%
1.0
1.2
1.4
1.6
1.8
2.0
peak hand speed (m/s)