


Id: 1/2



Notes

- if U_{bat} dips below 4V, P-MOSFET turns on --> ESC's builtin caps might save power rail in case of current surge?
 - U_{Bat1} , U_{Bat2} needed by battery charger
 ! current issue! Jetson Orin NX accepts 5VDC-20VDC through barrel plug
 --> DC/DC buck converter could smooth voltage ripple caused by ESC but requires higher battery voltage (currently at 7.2V, need at least 9V)
 = either add switching regulator or add capacitors for voltage ripple
 = gamble for now and use P-Mosfet supply with 1uF cap
 ? Jetson Orin NX Carrier Board includes decoupling caps, issue fixed?

Sheet: /BMU/
 File: BMU.kicad_sch

Title:

Size: A4
 KiCad E.D.A. 10.0.4

Date:

Rev:

Id: 2/2