

M

1020

Pt1000

Temperature range (M: upto 600 °C)

**Dimensions L in mm, B in 1/10mm
(In the eg. : L = 10mm; B = 2mm)**

Nominal resistance (Pt 1000)