

Piezoelectric effect Measuring Tasks

```
graph TD; A[Piezoelectric effect Measuring Tasks] --> B[Force]; A --> C[Torque]; A --> D[Pressure]; A --> E[Acceleration]; A --> F[Vibration]; A --> G[Vibration Analysis]; A --> H[Gas Concentration];
```

Force

Torque

Pressure

Acceleration

Vibration

Vibration
Analysis

Gas
Concentra-
tion