Gas Leakage monitoring & Alerting system for Industries

Assignment-3

CODE:

BLINKING LED

import RPi.GPIO as GPIO

import time

LED=2

GPIO.setmode(GPIO.BCM)

GPIO.setup(LED, GPIO.OUT)

While(1):

GPIO.output(LED,GPIO.HIGH)

time.sleep(1)

GPIO.output(LED, GPIO.LOW)

Time.sleep(1)

CODE 2:

#TRAFFIC LED

import RPi.GPIO as GPIO

import time

RED=2

YELLOW=3

GREEN=4

GPIO.setmode(GPIO.BCM)

GPIO.setup(2, GPIO.OUT)

```
GPIO.setup(3, GPIO.OUT)

GPIO.setup(4, GPIO.OUT)

While(1):
GPIO.output(2,GPIO.HIGH)
time.sleep(10)
GPIO.output(2, GPIO.LOW)
GPIO.output(3,GPIO.HIGH)
time.sleep(10)
GPIO.output(3, GPIO.LOW)
GPIO.output(4,GPIO.HIGH)
time.sleep(10)
```

GPIO.output(4, GPIO.LOW)