Gas Leakage monitoring & Alerting system for Industries

Assignment-2

CODE:

```
import random
def alert(t):
if t>40:
    print("alarm on")
else:
    print("alarm off")

while(1):
    temp=random.randint(25,100)
    humidity=random.randint(0,100)
    print(temp,humidity)

alert(temp)
print("\n")
```