## **INTERNET OF THINGS**

## **ASSIGNMENT - 4**

4. Write code and connections in wokwi for the ultrasonic sensor

```
const int TRIG_PIN = 7;
const int ECHO PIN = 8;
const unsigned int MAX DIST = 23200;
void setup() {
 pinMode(TRIG_PIN, OUTPUT);
 digitalWrite(TRIG_PIN, LOW);
 pinMode(ECHO_PIN, INPUT);
void loop() {
 unsigned long t1;
 unsigned long t2;
 unsigned long pulse_width;
 float cm;
 float inches;
 digitalWrite(TRIG_PIN, HIGH);
 delayMicroseconds(10);
 digitalWrite(TRIG_PIN, LOW);
 while (digitalRead(ECHO_PIN) == 0);
 while (digitalRead(ECHO_PIN) == 1);
 t2 = micros();
 pulse\_width = t2 - t1;
 cm = pulse\_width / 58.0;
 inches = pulse_width / 148.0;
if ( pulse_width > MAX_DIST ) {
  Serial.println("Out of range");
 } else {
  Serial.print(cm);
  Serial.print(" cm \t");
  Serial.print(inches);
  Serial.println(" in");
 // Wait at least 60ms before next measurement
```

delay(60);

## **OUTPUT:**

