## **ASSIGNMENT-4**


Assignment Date	26 October 2022
Team ID	PNT2022TMID15087
Project Name	Gas Leakage monitoring & Alerting system for Industries
Maximum Marks	2 Marks

Write code and connections in wokwi for ultrasonic. Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.

## **Solution:**

```
#define ECHO PIN 2
#define TRIG PIN 3
#define organization = "mmbh4c"
#define deviceType = "Ultrasonic"
#define deviceId = "1112"
#define authMethod = "use-token-auth"
#define authToken = "123456789"
void setup() {
 Serial.begin(9600);
 pinMode(TRIG PIN, OUTPUT);
float readDistanceCM() {
```

```
digitalWrite(TRIG_PIN, HIGH);
 int duration = pulseIn(ECHO PIN, HIGH);
void loop() {
  Serial.println("person detected ");
Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
```



## IBM Cloud Device Recent Events

