Team ID	PNT2022TMID44448
Submitted by	K.Nithya
Topic	Signs With smart connectivity
	for better road safety
Assignment	Write code and connections in
	wokwi for ultrasonic sensor.
	Whenever distance is less than
	100cms send "alert" to IBM
	cloud
	and display in device recent
	events.

Program Code:

```
#include "Ultrasonic.h"
Ultrasonic ultrasonic(8,13);
int distance;
void setup() {
   Serial.begin(9600);
  }
  void loop() {
   distance = ultrasonic.read();
   Serial.print("Distance in CM: ");
   Serial.println(distance);
   If (distance <100)
   Serial.print("alert ");
   Serial.println();
   delay(3000);
}</pre>
```

Output:

