Team ID	PNT2022TMID44448		
Submitted By	Priyadharsini T		
Topic	Signs With smart connectivity		
	for better road safety		
Assignment	Write code and connections in		
	wokwi for ultrasonic sensor.		
	Whenever distance is less than		
	100cms send "alert" to IBM cloud		
	and display in device recent events.		

Program Code:

```
#include "Ultrasonic.h"
Ultrasonic ultrasonic(8,13);
int distance;
void setup() {
   Serial.begin(9600);
   }
   void loop() {
    distance = ultrasonic.read();
   Serial.print("Distance in CM: ");
   Serial.println(distance);
   If (distance <100)
        Serial.print("alert ");
   Serial.println();
   delay(3000);
   }
}</pre>
```

Output:

