Assignment -3
To get temperature and humidity value

Assignment Date	09 October 2022
Student Name	Ms. Vishali S
Student Roll Number	9517201903175
Maximum Marks	2 Marks

Question-1:

Python program for led blinking.

Solution:
```
import RPI.GPIO as GPIO
from time import sleep
GPIO.setmode(GPIO.BOARD)
R=13
Y=12 G=8
while True:
        GPIO.output (13, GPIO.HIGH) sleep (5)
        GPIO.output(12, GPIO.HIGH) sleep(5)
        GPIO.output(8, GPIO.HIGH)

        sleep(5)
```

Question-2:
Python program for traffic light.

Solution:

```
import RPi.GPIO as GPIO

from time import sleep

GPIO.setwarnings(False)

GPIO.setmode (GPIO.BOARD)

GPIO.setup(8, GPIO.OUT, initial=GPIO.LOW)  while True:
        GPIO.output (8, GPIO.HIGH) sleep(1)
        GPIO.output (8, GPIO.LOW) sleep(1)
```