IBM - Assignment

Blinkinglight.py

```
import RPi.GPIO as GPIO
import time
#assign numbering for the GPIO using BCM
GPIO.setmode(GPIO.BCM)
#assign number for the GPIO using Board
#GPIO.setmode(GPIO.BOARD)
cnt = 0
MAIL_CHECK_FREQ = 1 # change LED status every 1 seconds
RED_LED = 4
GPIO.setup(RED_LED, GPIO.OUT)
while True:
ifcnt == 0 :
GPIO.output(RED_LED, False)
cnt = 1
else:
GPIO.output(RED_LED, True)
cnt = 0
time.sleep(MAIL_CHECK_FREQ)
GPIO.cleanup()
```

Trafficlight.py

```
from gpiozero import Button, TrafficLights, Buzzer
from time import sleep
buzzer = Buzzer(15)
button = Button(21)
lights = TrafficLights(25, 8, 7)
while True:
      button.wait_for_press()
      buzzer.on()
      light.green.on()
      sleep(1)
      lights.amber.on()
      sleep(1)
      lights.red.on()
      sleep(1)
      lights.off()
      buzzer.off()
```