## SENDING DATA FROM RASPBERRY-PI TO IBM WATSON

TeamID: PNT2022TMID04029


Team Members: Devaprakash S, Sathish V, Boobalan H, Sathishkumar K

Project: Gas Leakage Monitoring and Alerting System for Industries.


Steps to followed to send data from raspberry PI to IBM

Watson:


**Step 1:** GO to IOT in resource list.




Step 2: Click launch button.



**Step 3:** Go to Browse option and create a device. Enter detail in add device option




Step 4: Click Finish button.




## **Step 5:** Click stimulation running menu in below and Enter following code in JSON file:


{ "Hazardous Gas": random(0,100), "Temperature": random(0,100), "Pressure":random(0,100), "Humidity": random(0,100) }



Step 6: Create boards and cards for virtualization of data:



**Step 7:** Create boards



**Step 8:** Finally card generated different device.