GAS LEAKAGE MONITORING AND ALERTING SYSTEM FOR INDUSTRIES

Assignment 2

Problem Statement:

Build a python code, Assume you get temperature and humidity values (generated with random function to a variable) and write a condition to continuously detect alarm in case of high temperature.

Code:

```
#A python code assume you get temperature and humidity values generated with
alarm in case of high temperature
def temp sensor(name):
    k=True
              print("PRESS ctrl+c SWITCH OFF THE ALARM ")
while k==True:
                           import random
                                                 import time
temperature=random.uniform(35,90)
                                          print (f"The current
temperature is {temperature:.2f}°C")
humidity=random.randint(30,100)
                                        print(f"Humidity is
{humidity}%")
                      if temperature>60:
            print(f" ≝ ≝ BEEP!!!!BEEP!!!! ≝ ≝ \n The temperature
has exceeded to {temperature:.2f}°C \n press BREAK to stop the alarm")
while temperature>60:
                                 k=str(input())
                                                             k=k.upper()
if k=="BREAK" :
                break
else:
                print('''Uh-oh I guess you've used wrong word kindly type
"BREAK" to stop the alarm ''')
continue
                     break
         if
temperature>60:
            print("The alarm has been switched off successfully")
else:
            print("The temperature is normal")
```

```
time.sleep(7)
k=True
name=str(input("ENTER YOUR USERNAME: ")) print("\tASSIGNMENT 2 -
DETECTING ALARM IN CASE OF HIGH TEMPERATURE") temp_sensor(name)
```

Output:

```
Install the latest PowerShell for new features and improvements! https://aka.ms/PSWindows

PS.C:\Zmmpp\htdocs\sms.igniter>& %_C:\Program Files\Python310/python.exe* c:\Zmmpp/htdocs\sms.igniter>\sms.igniter>& %_C:\Zmmpp\htdocs\sms.igniter>& XSIGNIFOR THE ALARM
The current temperature is 68.28°C
Hamidity is 60%

WE BEPI!!|BEEPI!!|

The temperature has exceeded to 68.28°C
press BREAK to stop the alarm
hreak
The alarm has been switched off successfully
The current temperature is 63.11°C
press BREAK to stop the alarm
break
The alarm has been switched off successfully
The current temperature is 52.14°C
Hamidity is 70%
The temperature is normal
The current temperature is 56.68°C
Hamidity is 70%
The temperature is 66.88°C
press BREAK to stop the alarm
break
The temperature is normal
The current temperature is 66.88°C
press BREAK to stop the alarm
break
The temperature is 86.88°C
press BREAK to stop the alarm
break
The temperature is 86.88°C
press BREAK to stop the alarm
break
The temperature has exceeded to 86.88°C
press BREAK to stop the alarm
break
The temperature has been switched off successfully
The current temperature is 66.30°C
Hamidity is 90%

WE BEPI!!!BEEP!!!! EEP!!!

WE BEPI!!!BEEP!!!
```