
Code:

```
void setup()
   Serial.begin(9600);
   pinMode(12,OUTPUT);
   pinMode(2,INPUT);
• }
  void loop()
   int motion=digitalRead(2);
   double data=analogRead(A0);
   double n=data/1024;
   Serial.print("Converted Analog Data: ");
   Serial.println(n);
   double volt=n*5; //because connected to 5v
   Serial.print("Voltage data: ");
```



```
    Serial.println(volt);

    double off=volt-0.5;

Serial.print("Offset Data: ");
Serial.println(off);

    double temperature=off*100;

    Serial.print("Temperature Data: ");

    Serial.println(temperature);

if(motion==1 && temperature<60)</li>
tone(12,100);

    else if(motion==0 && temperature>60)

tone(12,200);

    else if(motion==1 && temperature>60)

  noTone(12);

    else if(motion==0 && temperature<60)</li>

   noTone(12);
•}
```

