
ULTRASONIC SENSORS



```
#define ECHO_PIN 2
#define TRIG_PIN 3
void setup() {
   Serial.begin(115200);
   pinMode(LED_BUILTIN,OUTPUT);
   pinMode(TRIG_PIN, OUTPUT);
   pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
   digitalWrite(TRIG_PIN, LOW);
```

```
delayMicroseconds(2);
 digitalWrite(TRIG_PIN, HIGH);
 delayMicroseconds(10);
 digitalWrite(TRIG_PIN, LOW);
 int duration = pulseIn(ECHO_PIN, HIGH);
 return duration * 0.034/2;
}
void loop() {
 float distance = readDistanceCM();
 bool isNearby = distance < 100;
 digitalWrite(LED_BUILTIN, isNearby);
 Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
 delay(100);
https://wokwi.com/projects/346497866532913748
```