
IOT ENABLED SMART FARMING APPLICATION SPRINT DELIVERY – 4 Team ID:PNT2022TMID04037

5.5 Receiving commands from IBM cloud using Python program


```
import time import
Sys
import ibmiotf.application
import ibmiotf.device import
random
#Provide your IBM Watson Device Credentials
organization = "x0cl0i"
deviceType="nodemcu" device Id = "sensor "
authMethod = "use-token-auth" authToken =
"6GsCaVQ3-PfYy+j3ts"
# Initialize GPIO
def myCommandCallback(cmd): print("Command
received: %s" % cmd.data['command'])
status=cmd.data['command'] if status=="motoron":
print ("motor is on") elif status == "motoroff":
                 print ("motor is off")
                                                   else
    print ("please send proper command")
try:
       deviceOptions = {"org": organization, "type": deviceType, "id": deviceId,
"auth-method": authMethod, "auth-token": authToken}
deviceCli = ibmiotf.device.Client(deviceOptions)
```

```
except Exception as e:
      print("Caught exception connecting device: %s" % str(e))
sys.exit()
# Connect and send a datapoint "hello" with value "world" into the cloud as
an event of type "greeting" 10 times deviceCli.connect()
while True:
    #Get Sensor Data from DHT11
temp=random.randint(90,110)
Humid=random.randint(60,100)
Mois=random. Randint(20,120)
  data = { 'temp' : temp, 'Humid': Humid,
'Mois': Mois}
    #print data
                   de
f
myOnPublishCallback():
      print ("Published Temperature = %s C" % temp, "Humidity = %s %%" %
Humid, "Moisture =%s deg c" % Mois "to IBM Watson")
      success = deviceCli.publishEvent("IoTSensor", "json", data,
qos=0, on publish=myOnPublishCallback) if not success:
      print("Not connected to IoTF")
time.sleep(10)
    deviceCli.commandCallback = myCommandCallback
# Disconnect the device and application from the cloud
deviceCli.disconnect(
```

6. Flow Chart



7. Observations & Results







iot

