Develop a Python Script

Team ID	PNT2022TMID22430
Project Name	Project – Smart waste management system for Metropolitan cities

<u>Develop a python code for publishing the bin values to the IBM IoT Platform.</u>

The Python script is developed and published to cloud.

```
import time
import sys
import ibmiotf.application
import ibmiotf.device
import random
#Provide your IBM Watson Device Credentials
organization = "32ws5h"
deviceType = "Ultrasonic_sensor"
deviceId = "554517"
authMethod = "token"
authToken = "12345678"
# Initialize GPIO
def myCommandCallback(cmd):
  print("Message received from IBM IOT Platform : %s" % cmd.data['ALERT'])
  status=cmd.data['ALERT']
  if status=="BIN FULL":
    print ("Empty the bin immediately")
try:
       deviceOptions = {"org": organization, "type": deviceType, "id": deviceId, "auth-method":
authMethod, "auth-token": authToken}
       deviceCli = ibmiotf.device.Client(deviceOptions)
       #.....
except Exception as e:
       print(" Caught exception connecting device: %s" % str(e))
       sys.exit()
deviceCli.connect()
#SENSOR DATA
```

```
Garbage_level=0
Garbage_weight=0
while True:
    #Get Sensor Data from DHT11
    Garbage_level=Garbage_level+random.randint(90,110)
    Garbage weight=Garbage weight+random.randint(60,100)
    data = { 'Garbage level(%)' : Garbage_level, 'Garbage weight(g)': Garbage_weight , 'Location':
"10, Gandhi nagar, Adayar"}
    def myOnPublishCallback():
      print ("Published Garbage level(%) = %s %" % Garbage_level, "Garbage weight(g) = %s %" %
Garbage_weight, "to IBM Watson")
    success = deviceCli.publishEvent("Ultrasonic sensor", "json", data, gos=0,
on publish=myOnPublishCallback)
    if not success:
      print("Not connected to IoTF")
    time.sleep(10)
    deviceCli.commandCallback = myCommandCallback
```

Disconnect the device and application from the cloud deviceCli.disconnect()

```
*python script.py - C:/Users/Jayasri/Desktop/python script.py (3.11.0)*
File Edit Format Run Options Window Help authMethod = "token" authToken = "12345678"
# Initialize GPIO
def myCommandCallback(cmd):
    print("Message received from IBM IOT Platform : %s" % cmd.data['ALERT'])
    status=cmd.data['ALERT']
    if status=="BIN FULL":
        print("Empty the bin immediately")
           deviceOptions = {"org": organization, "type": deviceType, "id": deviceId, "auth-method": authMethod, "auth-token": authToken}
           deviceCli = ibmiotf.device.Client(deviceOptions)
 except Exception as e:
    print(" Caught exception connecting device: %s" % str(e))
    sys.exit()
deviceCli.connect()
#SENSOR DATA
Garbage_level=0
Garbage_weight=0
           #Get Sensor Data from DHT11
          Garbage_level=Garbage_level+random.randint(90,110)
Garbage_weight=Garbage_weight+random.randint(60,100)
           data = { 'Garbage level(%)' : Garbage level, 'Garbage weight(g)': Garbage weight, 'Location': "10, Gandhi nagar, Adayar"}
          def myOnPublishCallback():
    print ("Published Garbage level(%) = %s %" % Garbage_level, "Garbage weight(g) = %s %" % Garbage_weight, "to IBM Watson")
           success = deviceCli.publishEvent("Ultrasonic_sensor", "json", data, qos=0, on_publish=myOnPublishCallback)
                print("Not connected to IoTF")
          time.sleep(10)
           deviceCli.commandCallback = myCommandCallback
   Disconnect the device and application from the cloud
deviceCli.disconnect()
```