## EXCEL ENGINEERING COLLEGE DEPARTMENT OF INFORMATION TECHNOLOGY

## **IOT ASSIGNMENT -1**

## **SMART SOLUTION FOR RAILWAYS**

```
int t=2;
int e=3;
void setup()
{
 Serial.begin(9600);
pinMode(t,OUTPUT);
pinMode(e,INPUT);
pinMode(12,OUTPUT);
}
void loop()
{
 //ultrasonic sensor
digitalWrite(t,LOW);
digitalWrite(t,HIGH);
delayMicroseconds(10);
digitalWrite(t,LOW); float
dur=pulseIn(e,HIGH); float
dis=(dur*0.0343)/2;
 Serial.print("Distance is: ");
 Serial.println(dis);
  //LED ON
if(dis>=100)
 { digitalWrite(8,HIGH);
 digitalWrite(7,HIGH);
```

```
}
//Buzzer For ultrasonic Sensor
if(dis>=100)
{
for(int i=0; i<=30000; i=i+10)
{
tone(12,i);
delay(1000);
noTone(12);
delay(1000);
}
}
 //Temperate Sensor
double a= analogRead(A0);
double t=(((a/1024)*5)-0.5)*100;
Serial.print("Temp Value: ");
Serial.println(t); delay(1000);
//LED ON
if(t>=100)
{
digitalWrite(8,HIGH);
digitalWrite(7,HIGH);
}
//Buzzer for Temperature Sensor
if(t>=100)
{
for(int i=0; i<=30000; i=i+10)
{
```

```
tone(12,i); delay(1000); noTone(12); delay(1000);
}

//LED OFF
if(t<100)
{
    digitalWrite(8,LOW);
    digitalWrite(7,LOW);
}</pre>
```

