Stage 1 coding for GAS LEAKAGE MONITORING AND ALERTING SYSTEM

```
#include <LiquidCrystal_I2C.h>
// Set the LCD address to 0x3F for 16 chars and 2 line display
LiquidCrystal_I2C lcd (0x3F, 16, 2);
void setup()
 // initialize the LCD display
 lcd.init();
 // Turn on the blacklight and print a message.
 lcd.backlight();
 //lcd.print("Hello, world!");
}
void loop()
lcd.clear();
lcd.print("Hello World!");
delay(1000);
lcd.clear();
```

```
lcd.print("I'm powered by");
lcd.setCursor(3,1);
lcd.print("Arduino!");
delay(1000);
lcd.clear();
}
```