SENDING DATA FROM RASPBERRY-PI TO IBM WATSON

TeamID: PNT2022TMID04047


Team Members: Suvanthini S, Nishanthini P, Priyankka shree K J, Harini C K

Project: Gas Leakage Monitoring and Alerting System for Industries.


Steps to followed to send data from raspberry PI to IBM

Watson:


Step 1: GO to IOT in resource list.




Step 2: Click launch button.



Step 3: Go to Browse option and create a device. Enter detail in add device option



Step 4: Click Finish button.




Step 5: Click stimulation running menu in below and Enter following code in JSON file:

```
{ "Hazardous Gas": random(0,100),
```


[&]quot;Temperature": random(0,100),

[&]quot;Pressure":random(0,100),


[&]quot;Humidity": random(0,100) }



Step 6: Create boards and cards for virtualization of data:



Step 7: Create boards



Step 8: Finally card generated different device.