PROJECT DEVELOPMENT PHASE

SPRINT-1

Team ID PNT2022TMID27352

Project Name Industrial Specific Fire Management System

PYTHON CODE:

```
import time
import sys
import ibmiotf.application
import ibmiotf.device
import random
#Provide your IBM Watson Device Credentials
organization = "ms21j6"
deviceType = "hardware"
deviceId = "abcd"
authMethod = "token"
authToken = "12345678"
# Initialize GPIO
def myCommandCallback(cmd):
print("Command received: %s" % cmd.data['command'])
status=cmd.data['command']
if status=="lighton":
print ("led is on")
elif status == "lightoff"
print ("led is off")
```

```
else:
print ("please send proper command")
try:
deviceOptions = {"org": organization, "type": deviceType, "id":
deviceId, "auth-method": authMethod, "auth-token": authToken}
deviceCli = ibmiotf.device.Client(deviceOptions)
#.....
except Exception as e:
print("Caught exception connecting : %s" % str(e))
sys.exit()
# Connect and send a datapoint "hello" with value "world" into the
cloud as an event of type "greeting" 10 times
deviceCli.connect()
while True:
#Get Sensor Data from DHT11
temp=random.randint(90,110)
Humid=random.randint(60,100)
data = { 'temp' : temp, 'Humid': Humid }
#print data
def myOnPublishCallback():
print ("Published Temperature = %s C" % temp, "Humidity =
%s %%" % Humid, "to IBM Watson")
success = deviceCli.publishEvent("IoTSensor", "json", data,
```

```
qos=0, on_publish=myOnPublishCallback)

if not success:

print("Not connected to IoTF")

time.sleep(10)

deviceCli.commandCallback = myCommandCallback
```

Disconnect the device and application from the cloud deviceCli.disconnect()

OUTPUT:

