VELAMMAL ENGINEERING COLLEGE ELECTRONICS AND COMMUNICATION ENGINEERING

SMART FARMERS - IOT ENABLED FARMING APPLICATION ASSIGNMENT – 4

BY:
PARVEEN REHANA

(113219041080)

Question:

WRITE CODE AND CONNECTIONS IN WOKWI FOR ULTRASONIC. WHENEVER DISTANCE IS LESS THAN 100 CMS SEND "ALERT" TO IBM CLOUD AND DISPLAY IN DEVICE RECENT EVENTS.

CODE:

```
#define ECHO PIN 2
#define TRIG PIN 3
#define organization = "mmbh4c"
#define deviceType = "Ultrasonic"
#define deviceId = "pga460 sensor"
#define authMethod = "use-token-auth"
#define authToken = "123456789"
void setup() {
Serial.begin(9600);
pinMode(TRIG PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
```

```
int duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
}
void loop() {
  float distance = readDistanceCM();
  if(distance <= 100)
  {
    Serial.println("person detected ");
  }
  else {
    Serial.print("Measured distance: ");
    Serial.println(readDistanceCM());
  }
  delay(1000);
}</pre>
```

OUTPUT:

