Code:

```
#include "Ultrasonic.h"
Ultrasonic ultrasonic (12, 13);
int distance;
void setup() {
  Serial.begin(9600);
}
void loop() {
  // Pass INC as a parameter to get the distance in inches
  distance = ultrasonic.read(CM);
  Serial.print("Distance in CM: ");
Serial.println(distance);
                              if
(distance < 100)
  Serial. print("alert");
Serial.println();
                     delay(1000);
```

Output:

