## **IOT ASSIGNMENT 2**

**TOPIC:** Gas leakage monitoring and alerting system for industries

## NAME:

**KARTHICK V** 

## CODE:

```
import random while(True):
```

a=random.randint(10,100)

b=random.randint(10,100)

if(a>35 and b>65): print("HIGH TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS ON") continue

elif(a<35 and b<65):
print("NORMAL TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS OFF")
break

**OUTPUT:-**

