Gas Leakage monitoring & Alerting system for Industries

Assignment-3

CODE:

BLINKING LED

import RPi.GPIO as GPIO

import time

 $LED_PIN = 17$

GPIO.setmode(GPIO.BCM)

GPIO.setup(LED_PIN, GPIO.OUT)

GPIO.output(LED_PIN, GPIO.HIGH)

time.sleep(1)

GPIO.output(LED_PIN, GPIO.LOW)

GPIO.cleanup()

CODE 2:

#TRAFFIC LED

from gpiozero import LED

from time import sleep

red = LED(22)

amber = LED(27)

green = LED(17)

while(True):

red.on()

sleep(1)

amber.on()
sleep(1)
green.on()
sleep(1)