Gas Leakage monitoring & Alerting system for Industries


Assignment-1

CODE:


```
void setup(){
 Serial.begin(9600);
 pinMode(2,INPUT);
 pinMode(12,OUTPUT);
void loop(){
 int motion=digitalRead(2);
 Serial.print("Position is :");
 Serial.println(motion);
 double data=analogRead(A2);
 double n = \frac{data}{1024};
 double volt = n*5;
 double off=volt-0.5;
 double temp=off*100;
 Serial.print("temp value :");
 Serial.println(temp);
 if(motion==1&&temp>=60) {
   tone(12,3);
 }
 else if(temp>=60) {
   tone(12,4);
 else if(motion==1) {
   tone(12,5);
 }
```

```
else{
    noTone(12);
}
```

OUTPUT:



Working of PIR sensor



Working of both PIR and temperature sensor with piezo alarm

