```
TITLE: HOME AUTOMATION USING SENSORS.
TEAM MEMBER: P. ABIRAMI
CODE:
Int t=2;
Int e=3;
Void setup()
{
Serial.begin(9600);
 pinMode(t,OUTPUT);
pinMode(e,INPUT);
pinMode(12,OUTPUT);
}
Void loop()
//ultrasonic sensor
digitalWrite(t,LOW);
digitalWrite(t,HIGH);
delayMicroseconds(10);
digitalWrite(t,LOW);
float dur=pulseIn(e,HIGH);
float dis=(dur*0.0343)/2;
Serial.print("Distance is: ");
 Serial.println(dis);
  //LED ON
 If(dis>=100)
{
```

```
digitalWrite(8,HIGH);
 digitalWrite(7,HIGH);
}
//Buzzer For ultrasonic Sensor
If(dis>=100)
{
For(int i=0; i<=30000; i=i+10)
{
Tone(12,i);
Delay(1000);
noTone(12);
delay(1000);
}
}
 //Temperate Sensor
Double a= analogRead(A0);
Double t=(((a/1024)*5)-0.5)*100;
Serial.print("Temp Value: ");
Serial.println(t);
Delay(1000);
//LED ON
If(t>=100)
```

```
{
  digitalWrite(8,HIGH);
  digitalWrite(7,HIGH);
}
//Buzzer for Temperature Sensor
If(t>=100)
{
For(int i=0; i<=30000; i=i+10)
{
Tone(12,i);
Delay(1000);
noTone(12);
delay(1000);
}
}
 //LED OFF
If(t<100)
  digitalWrite(8,LOW);
 digitalWrite(7,LOW);
}
CIRCUIT DIAGRAM:
```

