## Assignment-4

## Write code and connections in wokwi for ultra sonic sensor. When ever distance is less than 100 cm send "alert" to ibm cloud and display in device recent events

Date	22 October 2022
TeamID	PNT2022TMID02387
ProjectName	IOT-based Smart Crop Protection System
	forAgriculture
MaximumMarks	2 Marks

## **PROGRAM:**

```
//ARDUINOPINS(TRIGGERPIN,ECHO
PIN)const int TRIG_PIN=
7;constintECHO_PIN=8;

//Anythingover400cm(23200uspulse)is"outofrange"constunsignedintmax_
dist=23200;
voidsetup()
{

//TheTriggerpinwilltellthesensortorangefindpinMode(TRIG_PIN,OUTPUT)
;
digitalWrite(TRIG_PIN,LOW);
//SetEchopinasinputto measurethe time durationofpulsereturning backfrom thedistancesensorpinMode(ECHO_PIN,INPUT);
```

```
//We'llusethe serialmonitortoviewthesensoroutput
  Serial.begin(9600);
voidloop(){
  unsigned long t1;unsignedlong
  t2; unsigned longpulse_width;
  float cm;floatinches;
  //Holdthetriggerpinhighforatleast10us
  digitalWrite(TRIG PIN,
  HIGH);delayMicroseconds(10);
  digitalWrite(TRIG PIN,LOW);
  //Waitforpulseonechopin
  while(digitalRead(ECHO PIN)==0);
  // Measure how long the echo pin was held high (pulsewidth)//Note:
  themicros()counterwilloverflowafter
  ~70 mint1 = micros(); while(digitalRead(ECHO_PIN)== 1);t2=micros();
  pulse width=t2-t1;
  // Calculate distance in centimeters and inches. The constants //arefoundinthe
  datasheet,andcalculatedfromtheassumedspeed
  //ofsoundinairatsealevel(~340m/s).cm=pulse widt
  h/58.0;
  inches=pulse_width/148.0;
  //Printoutresults
  if(pulse width >max dist){
    Serial.println("Outofrange");
  } else
    {Serial.println("**********************************);Serial.print("Distance
    Measuredincm:");
```

## OUTPUT:



