Name: ANUSHREE S Rollno: 727719EUEC015

ASSIGNMENT 2 - Temperature and humidity sensing and alarm automation

CODE:

```
import random
from time import sleep
while True:
    t= random.randint(1,50)
    print("Temperature=",t)
    h= random.randint(1,50)
    print("Humid=",h)
    if(t>=50 and h<35):
        print("On")
    else:
        print("Off")
    sleep(3)</pre>
```

OUTPUT:

```
File Edit View Insert Runtime Tools Help All changes saved
                                                                                                                           ... RAM □ □ □ □ □ □ □
+ Code + Text
                                                                                                                                 ↑ ↓ ⊖ 目 ‡
     import random
      from time import sleep
      while True:
      t= random.randint(1,50)
       print("Temperature=",t)
       h= random.randint(1,50)
       print("Humid=",h)
       if(t>=50 and h<35):
         print("On")
         print("Off")
     sleep(3)
      Temperature= 25
      Humid= 41
      Off
      Temperature= 46
      Humid= 3
      Temperature= 49
      Humid= 31
      Off
      Temperature= 17
      Humid= 26
      Off
ve.google.com/drive/search?q=owner%3Ame (type%3Aapplicatio...
                                                                    Executing (56s) Cell
```