PYTHON CODE (GAS, TEMPERATURE, HUMIDITY, PRESSURE)

Team ID	PNT2022TMID18536
Project Name	GAS LEAKAGE MONITORING AND ALERTING SYSTEM FOR
	INDUSTRIES

PYTHON CODE:

import random

```
print('Random number =',str(random.randint(0,100)))
print('Temperature=',str(random.randint(0,100)))
print('Humidity=',str(random.randint(0,100)))
print('Pressure=,str,random.randint(0,100)))
```

OUTPUT:

```
| IDLE Shell 3.10.2 | Tiple Edit Format Run Options Window Help | Tiplot Fandom print ("Hazardous Gas Level-", str(random.randint(0,100))) | Print ("Temperatures", str(random.randint(0,100))) | Print ("Pressure-", str(random.randint(0,100)) | Print ("Press
```





