**TITLE:** Gas Leakage monitoring & Alerting system for Industries

SPRINT PLAN	Identify the Problem	1
	Prepare a Abstract, Problem Statement	2
	List a required object needed	3
	Create a Code and Run it	4
	Make a Prototype	5
	Test with the created code and check the designed prototype is	6
	Solution for the Problem is Found!!	7